

ASS. REC. BY:

REF:

LPC / 2000 5530/KK

Kka3n2

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBF 1646A

Yr Regn: _____

07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

NIS NV200

c.c

1597

Colour _____

A. Grey

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

98698

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VM20

09594

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

175/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Goodridge

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

30/14/20

D.O.I. _____

5/5/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/5

11 Pm @ 38501. Confirmed

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

LONPAC INSURANCE BHD
300
BEACH RD #17-04/07
CONCOURSE THE
SINGAPORE 199555

Contact : -

Not Notified
11 Sep @ 3850.
Running After Pairs
3 days

Estimate : QUOT202005-000017(00)

Date : 04/05/2020
Vehicle No. : GBF1646A
Make/Model : NISSAN NV200
Mileage (km) : 0
Chassis No. : VM20095949
Accident Date : 30/04/2020 00:00:00
Claim No. : YN8705C
Reference : JO202005-0028
Policy No. : D19MTPCVE0002336

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS :				
1	Rear RH fender	1.0	1,551.30	<i>B1</i> 1,551.30 ✓
2	RH taillamp	1.0	236.50	<i>CMY</i> 236.50 ✓
3	Rear bumper	1.0	481.50	<i>B1</i> 481.50 ✓
4	Rear bumper retainer	1.0	38.30	<i>D11</i> 38.30 ✓
5	RH slide door rail (ctr) <i>rubber type</i>	1.0	184.80	<i>SE</i> 184.80 ✓
6	RH slide door glass	1.0	1,240.00	<i>shattered</i> 1,240.00 ✓
List Total :				3,732.40
10% Discount S\$				373.24
				3,359.16
SPECIAL NET :				
1	Glass sealant	2.0	40.00	<i>me</i> 80.00 ✓
SPECIAL NET Total S\$:				80.00
LABOUR :				
- To check wiring and lighting	1.0	60.00	60.00	60.00 ✓
- To remove and refit reverse sensor	1.0	40.00	40.00	40.00 ✓
- To remove and refit rear RH fender glass	1.0	100.00	100.00	<i>601</i> 100.00
- To remove and refit RH slide door glass	1.0	100.00	100.00	<i>501</i> 100.00
- To remove and refit inner trims and upholstery	1.0	100.00	100.00	100.00 <i>601</i>
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	800.00	800.00	<i>6001</i> 800.00
- Spray painting on affected & replace parts	1.0	600.00	600.00	<i>4801</i> 600.00
				1,800.00

V-cool

8180 new 100%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

E. & O. Illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 5,239.16

GST 7% S\$: 366.74

Amount Due S\$: 5,605.90

for CITY AUTO PTE LTD