

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified             | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'ed | Status                                                          |
|------|----------------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 04 May 2020<br>16:42 |               | 04 May 2020<br>17:02<br><a href="#">Edit Adj Rpt</a> | <b>S\$7,350.00</b><br><a href="#">Edit Estimates</a> | <b>S\$7,350.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                           | Reference   | Claim Details                                                                                    | Documents                   | <a href="#">Show All</a>                                                                                       |
|------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                                 |             |                                                                                                  | <b>[Created by insurer]</b> |                                                                                                                |
| Insured: <b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G                                                                                |             |                                                                                                  |                             |                                                                                                                |
| Main Claimant: <b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369K                                                                            |             |                                                                                                  |                             |                                                                                                                |
| Vehicle Reg. No.: <b>SHC4412H</b>                                                                                                              |             | Date of Loss: 14/04/2020 07:00 - :59<br><b>[75 Months and 1 Days From LTA Reg Date (Man Yr)]</b> |                             |                                                                                                                |
| Claim Type: <b>TP / 623246</b>                                                                                                                 |             | Policy/Cover Note No.: 29141713 (Comprehensive)<br>Coverage: 01/02/2020 - 31/12/2020             |                             |                                                                                                                |
| Vehicle Reg. No. (Insured): <b>SLL3761L</b>                                                                                                    |             | Policy No. (Claimant): D-20095484MFSH                                                            |                             |                                                                                                                |
| Excess:                                                                                                                                        |             |                                                                                                  |                             |                                                                                                                |
| Repairer: <b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628                |             |                                                                                                  |                             |                                                                                                                |
| Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Desmond Lee Kerr Wen</b> ]          |             |                                                                                                  |                             |                                                                                                                |
| Claimant's Insurer: <b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311                                                                 |             |                                                                                                  |                             |                                                                                                                |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>OI SUN PIN</b> ] ... <b>[Imm.Advice due 05/05/2020]</b> |             |                                                                                                  |                             |                                                                                                                |
| Driver/Custodian (Insured): TAN KIA PENG (54 / Male) , NRIC: S1689043Z, Tel: +6597616863 Email:                                                |             |                                                                                                  |                             |                                                                                                                |
| Adj Asg. Remarks: Direct Survey by LKK.                                                                                                        |             |                                                                                                  |                             |                                                                                                                |
| <b>ASSOCIATED MAIL RECEIVED</b>                                                                                                                |             |                                                                                                  |                             | <a href="#">View All</a> <a href="#">Compose Case Mail</a>                                                     |
| There are no mail for this case.                                                                                                               |             |                                                                                                  |                             |                                                                                                                |
| <b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>                                                                                           |             |                                                                                                  |                             | <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |
| Due Date                                                                                                                                       | Priority    | Type                                                                                             | Task Group                  | Subject                                                                                                        |
| Handler                                                                                                                                        | Assigned By | Completed On                                                                                     | Created On                  | Done?                                                                                                          |
| No results.                                                                                                                                    |             |                                                                                                  |                             |                                                                                                                |



## Claim Documents

**\*SHC4412H (623246)**  
**[SLL3761L]**  
**TP**  
**SMRT TAXIS PTE LTD**  
**Apr 14 2020 7:00AM**  
**[GRAB RENTALS PTE LTD]**  
**SMRT Automotive Services Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

| Photos/Images |                 |                                   |  |           |       |
|---------------|-----------------|-----------------------------------|--|-----------|-------|
| 3 per page    |                 |                                   |  |           |       |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail | Print |
| 1             | 05/05/20 10:11  | Chassis Number                    |  | Load JPG  |       |
| 2             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 3             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 4             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 5             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 6             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 7             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 8             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 9             | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 10            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 11            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 12            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 13            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 14            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 15            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 16            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 17            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 18            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 19            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 20            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 21            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 22            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 23            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 24            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 25            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 26            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 27            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 28            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 29            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 30            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 31            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 32            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 33            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 34            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 35            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 36            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 37            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 38            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 39            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |
| 40            | 05/05/20 10:12  | General View                      |  | Load JPG  |       |

| Photos/Images |                 |                                   |                                                                                       | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|---------------------------------------------------------------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |                                                                                       | Thumbnail  | Print                               |
| 41            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 57            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 58            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 59            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 60            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 61            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 62            | 05/05/20 10:12  | General View                      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 63            | 05/05/20 10:12  | General View                      |   | Load JPG   | <input checked="" type="checkbox"/> |
| 64            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 65            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 66            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 67            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 68            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 69            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 70            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 71            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 72            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 73            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 74            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 75            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 76            | 05/05/20 10:12  | General View                      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 77            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 78            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 79            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 80            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 81            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 82            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 83            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 84            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 85            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 86            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 87            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 88            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 89            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 90            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 91            | 28/05/20 16:45  | Dismantled Parts                  |  | Load JPG   | <input checked="" type="checkbox"/> |
| 92            | 28/05/20 16:46  | After Repair Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 93            | 28/05/20 16:46  | After Repair Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page                                                                                   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                    | Print                               |
| 94            | 28/05/20 16:46  | After Repair Photo                |  Load JPG | <input checked="" type="checkbox"/> |

  

| Documentation |                 |                                           | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail                                                                                    | Print                               |
| 1             | 04/05/20 16:44  | Status of Driving Licence                 |  Load PDF |                                     |
| 2             | 04/05/20 16:47  | Estimate                                  |  Load PDF |                                     |
| 3             | 04/05/20 16:47  | TP Accident report                        |  Load PDF |                                     |
| 4             | 04/05/20 16:47  | TP police report                          |  Load PDF |                                     |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                    | Print                               |
| 1             | 01/06/20 15:01  | SUPPLEMENTARY                             |  Load PDF |                                     |

## Linked Accident Report Documents

| Assessment Reports |                |                                         | View                                                                                         | View in Browser | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------------|----------------------------------------------------------------------------------------------|-----------------|-------------------------------------|
| No                 | Finalized On   | Aspectus Consultancy Pte Ltd (Aspectus) | Thumbnail                                                                                    | Print           |                                     |
| 1                  | 14/04/20 11:17 | Accident Statement                      |  Load HTM |                 |                                     |

  

| Photos/Images |                |                                         | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|----------------|-----------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Finalized On   | Aspectus Consultancy Pte Ltd (Aspectus) | Thumbnail                                                                                      | Print                               |
| 1             | 14/04/20 11:07 | Accident Photo                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 2             | 14/04/20 11:07 | Accident Photo                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 3             | 14/04/20 11:07 | Accident Photo                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 4             | 14/04/20 11:07 | Accident Photo                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 5             | 14/04/20 11:07 | Accident Photo                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 6             | 14/04/20 11:07 | Accident Photo                          |  Load JPG  | <input checked="" type="checkbox"/> |
| 7             | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 8             | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 9             | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 10            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 11            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 12            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 13            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 14            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 15            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 16            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 17            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 18            | 14/04/20 11:07 | Accident Photo                          |  Load JPG | <input checked="" type="checkbox"/> |
| 19            | 14/04/20 11:07 | Identification Card                     |  Load JPG | <input checked="" type="checkbox"/> |
| 20            | 14/04/20 11:07 | Identification Card                     |  Load JPG | <input checked="" type="checkbox"/> |
| 21            | 14/04/20 11:07 | Driving License                         |  Load JPG | <input checked="" type="checkbox"/> |
| 22            | 14/04/20 11:07 | Driving License                         |  Load JPG | <input checked="" type="checkbox"/> |
| 23            | 14/04/20 11:07 | Driving License                         |  Load JPG | <input checked="" type="checkbox"/> |
| 24            | 14/04/20 11:07 | Driving License                         |  Load JPG | <input checked="" type="checkbox"/> |
| 25            | 14/04/20 11:16 | Police Report                           |  Load JPG | <input checked="" type="checkbox"/> |
| 26            | 14/04/20 11:16 | Police Report                           |  Load JPG | <input checked="" type="checkbox"/> |
| 27            | 14/04/20 11:16 | Police Report                           |  Load JPG | <input checked="" type="checkbox"/> |

  

| Documentation |                |                                         | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|----------------|-----------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Finalized On   | Aspectus Consultancy Pte Ltd (Aspectus) | Thumbnail                                                                                      | Print                               |
| 1             | 14/04/20 11:03 | Sketch Plan                             |  Load JPG | <input checked="" type="checkbox"/> |
| 2             | 14/04/20 11:03 | Sketch Plan #2                          |  Load JPG | <input checked="" type="checkbox"/> |

## Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/MSG20005535/QQF3S2**Date:** 01/06/2020REFERENCE

|                              |                                      |                             |          |
|------------------------------|--------------------------------------|-----------------------------|----------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 29141713 |
| <b>Claimant Vehicle No :</b> | SHC4412H                             | <b>Insured Vehicle No :</b> | SLL3761L |
| Date of Loss:                | 14/04/2020                           | Nature of Claim:            | TP       |
|                              |                                      | Claim No:                   | 623246   |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHC4412H</b>                   | Engine No:  | 2ZR1326168        |
| Make & Model:               | TOYOTA PRIUS TAXI, 1.8 (A)        | Chassis No: | JTDKN36U305721454 |
| Reg. Date:                  | 13/01/2014 (Man. Year: 2013)      | Odometer:   | 0 km              |
| Colour:                     | Maroon                            |             |                   |
| Engine Capacity:            | 1496 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65R15     | Rear Tyre Size:  | 195/65R15     |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 27,532.86         | 6,132.81          | 21,400.05         | 77.73         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,108.00          | 2,420.00          | 2,688.00          | 52.62         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>32,640.86</b>  | <b>8,552.81</b>   | <b>24,088.05</b>  | <b>73.80</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>7,350.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>32,640.86</b>  | <b>7,350.00</b>   | <b>25,290.86</b>  | <b>77.48</b>  |

INSPECTION

|                             |            |                                                                                                                   |
|-----------------------------|------------|-------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 04/05/2020 |                                                                                                                   |
| Date Inspected:             | 30/04/2020 | Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)<br>60 Woodlands Industrial Park E4<br>Singapore 757705 |
| Estimated Period of Repair: | 6.0 days   |                                                                                                                   |

**Adjuster:** OI SUN PIN**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                             |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 01 Jun 2020)               |
| <b>Parts:</b>        | 144                                                                                                                                                                          | TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                           |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SHC4412H)                                                                                                                                    |                                                             |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                             |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                             |

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition   | Repairer's | Amount      |
|-----|-----|----------|-------------------------------------|-------------|------------|-------------|
| 1   | 1   |          | *FENDER APRON SUB FRT/RH (DISC 30%) | Bent        | 637.80 F   | *446.46 F   |
| 2   | 1   |          | *SUPPORT SUB-ASSY (DISC 30%)        | Bent        | 1,460.40 F | *1,022.28 F |
| 3   | 1   |          | *BUMPER CLIPS (DISC 30%)<br>10pcs   | Necessary   | 16.10 F    | *11.27 F    |
| 4   | 1   |          | *COVER, FR (DISC 30%)               | Scratched   | 18.50 F    | *12.95 F    |
| 5   | 1   |          | *FENDER FRT/RH (DISC 30%)           | Crushed     | 723.40 F   | *506.38 F   |
| 6   | 1   |          | *NAME PLATE (HYBRID) (DISC 30%)     | Necessary   | 51.90 F    | *36.33 F    |
| 7   | 1   |          | *FENDER LINER FRT/RH (DISC 30%)     | Crushed     | 171.70 F   | *120.19 F   |
| 8   | 1   |          | *HOOD PANEL (DISC 30%)              | Bent        | 748.10 F   | *523.67 F   |
| 9   | 1   |          | *HOOD HINGE RH (DISC 30%)           | Bent        | 55.90 F    | *39.13 F    |
| 10  | 1   |          | *WIPER WASHER JAR (DISC 30%)        | Crushed     | 180.10 F   | *126.07 F   |
| 11  | 1   |          | *COOLANT REVERSE TANK (DISC 30%)    | Crushed     | 395.30 F   | *276.71 F   |
| 12  | 1   |          | *BUMPER FRT (DISC 30%)              | Crushed     | 482.00 F   | *337.40 F   |
| 13  | 1   |          | *NAME PLATE (HYBRID) (DISC 30%)     | Necessary   | 51.90 F    | *36.33 F    |
| 14  | 1   |          | *HEAD LAMP RH (DISC 10%)            | Crushed     | 945.20 F   | *850.68 F   |
| 15  | 1   |          | *LENS & BODY, FR TURN RH (DISC 10%) | Crushed     | 511.80 F   | *460.62 F   |
| 16  | 1   |          | *STICKER DECAL SMRT (DOOR) (SN)     | Necessary   | 60.00 F    | *60.00 F    |
| 17  | 1   |          | *COOLANT (SN)                       | Necessary   | 12.32 F    | *12.32 F    |
| 18  | 1   |          | *FENDER PROTECTOR FRT/RH UPPER      | Serviceable | 46.10 F    | *- F        |
| 19  | 1   |          | *FENDER LINER PAD, FR WHEEL RH      | Serviceable | 49.30 F    | *- F        |
| 20  | 1   |          | *TYRE                               | Serviceable | 126.74 F   | *- F        |
| 21  | 1   |          | *SENSOR, SPEED, FR RH               | Serviceable | 446.50 F   | *- F        |
| 22  | 1   |          | *SEALANT W/SCREEN                   | Serviceable | 37.00 F    | *- F        |
| 23  | 1   |          | *WHEEL HUB FRT                      | Serviceable | 549.70 F   | *- F        |
| 24  | 1   |          | *WIPER GARNISH COVER, RH            | Serviceable | 23.80 F    | *- F        |
| 25  | 1   |          | *WIPER WASHER INLET                 | Serviceable | 36.90 F    | *- F        |
| 26  | 1   |          | *MOTOR NO 1, WIPER WASHER JAR       | Serviceable | 239.00 F   | *- F        |
| 27  | 1   |          | *MOTOR NO 2, WIPER WASHER JAR       | Serviceable | 240.00 F   | *- F        |
| 28  | 1   |          | *INLET ASSY, AIR                    | Serviceable | 232.50 F   | *- F        |
| 29  | 1   |          | *WIRE, ENGINE ROOM, NO.3            | Serviceable | 242.00 F   | *- F        |
| 30  | 1   |          | *BRACKET, FR TURN UPPER RH          | Serviceable | 58.20 F    | *- F        |
| 31  | 1   |          | *BRACKET, FR TURN                   | Serviceable | 58.20 F    | *- F        |
| 32  | 1   |          | *BRACKET, FR TURN LOWER RH          | Serviceable | 26.00 F    | *- F        |
| 33  | 1   |          | *COVER, RADIATOR                    | Serviceable | 122.80 F   | *- F        |
| 34  | 1   |          | *STICKER DECAL SMRT (DOOR)          | Serviceable | 60.00 F    | *- F        |
| 35  | 1   |          | *HINGE LOWER RH/F, DOOR             | Serviceable | 90.10 F    | *- F        |
| 36  | 1   |          | *DOOR HINGE UPPER FRT/RH            | Serviceable | 80.50 F    | *- F        |
| 37  | 1   |          | *CHECK ASSY, FR DOOR,               | Serviceable | 150.30 F   | *- F        |
| 38  | 1   |          | *MIRROR LAMP RH                     | Serviceable | 65.30 F    | *- F        |
| 39  | 1   |          | *COVER, OUTER MIRROR, RH            | Serviceable | 107.40 F   | *- F        |
| 40  | 1   |          | *FENDER SEAL TO COWL SIDE RH        | Serviceable | 15.20 F    | *- F        |
| 41  | 1   |          | *FENDER PROTECTOR FRT/RH SIDE       | Serviceable | 113.90 F   | *- F        |
| 42  | 1   |          | *FENDER APRON FRT/RH                | Serviceable | 168.10 F   | *- F        |
| 43  | 1   |          | *QUARTER GLASS FRT/RH               | Serviceable | 234.90 F   | *- F        |
| 44  | 1   |          | *SHOCK ABSORBER FRT/RH              | Serviceable | 394.20 F   | *- F        |
| 45  | 1   |          | *SHOCK ABSORBER MOUNTING FRT, RH/LH | Serviceable | 193.80 F   | *- F        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's | Amount    |
|-----|-----|----------|------------------------------------------|---------------|------------|-----------|
| 46  | 1   |          | *SHOCK ABSORBER BEARING, FRT LH/RH       | Serviceable   | 34.00 F    | *- F      |
| 47  | 1   |          | *LOWER ARM FRT/RH                        | Serviceable   | 625.90 F   | *- F      |
| 48  | 1   |          | *JOINT ASSY, LWR BALL                    | Serviceable   | 195.60 F   | *- F      |
| 49  | 1   |          | *TIE ROD END RH                          | Serviceable   | 159.30 F   | *- F      |
| 50  | 1   |          | *HOOD HINGE LH                           | Serviceable   | 55.90 F    | *- F      |
| 51  | 1   |          | *HOOD LOCK                               | Serviceable   | 128.90 F   | *- F      |
| 52  | 1   |          | *RADIATOR HOSE, BYPASS NO.1              | Serviceable   | 37.20 F    | *- F      |
| 53  | 1   |          | *WIRE, ENGINE ROOM                       | Serviceable   | 5,567.10 F | *- F      |
| 54  | 1   |          | *BUMPER SUPPORT F/RH                     | Serviceable   | 76.40 F    | *- F      |
| 55  | 1   |          | *BUMPER ENERGY ABSORBER FRT              | Serviceable   | 78.80 F    | *- F      |
| 56  | 1   |          | *BUMPER REINFORCEMENT FRT                | Serviceable   | 498.40 F   | *- F      |
| 57  | 1   |          | *ARM SUB-ASSY, FR BUMPER RH              | Serviceable   | 250.40 F   | *- F      |
| 58  | 1   |          | *BUMPER GRILLE SUB-ASSY, LOWER           | Serviceable   | 311.10 F   | *- F      |
| 59  | 1   |          | *FOG LAMP RH                             | Serviceable   | 295.20 F   | *- F      |
| 60  | 1   |          | *EMBLEM FRONT                            | Serviceable   | 86.50 F    | *- F      |
| 61  | 1   |          | *HOOD END PANEL SEAL                     | Serviceable   | 35.50 F    | *- F      |
| 62  | 1   |          | *GRILLE, RADIATOR                        | Serviceable   | 310.60 F   | *- F      |
| 63  | 1   |          | *BUMPER LIP FRT                          | Serviceable   | 139.60 F   | *- F      |
| 64  | 1   |          | *BUMPER FRT ABSORBER LOWER               | Serviceable   | 127.70 F   | *- F      |
| 65  | 1   |          | *DOOR FRT/LH                             | Serviceable   | 894.40 F   | *- F      |
| 66  | 1   |          | *PILLAR, FR BODY                         | Repair        | 363.10 F   | *- F      |
| 67  | 1   |          | *DOOR FR/RH                              | Repair        | 894.40 F   | *- F      |
| 68  | 1   |          | *WHEEL DISC, FRONT                       | Repair        | 1,484.20 F | *- F      |
| 69  | 1   |          | *MOULDING BODY, RH                       | Repair        | 673.80 F   | *- F      |
| 70  | 1   |          | *FENDER FRT/LH                           | Repair        | 723.40 F   | *- F      |
| 71  | 1   |          | *SOLAR FILM (SN)                         | Not Necessary | 125.00 F   | *- F      |
| 72  | 1   |          | *WHEEL HUB FRT (DISC 30%)                | Jammed        | 549.70 F   | *384.79 F |
| 73  | 1   |          | *LOWER ARM FRT/RH (DISC 30%)             | Bent          | 625.90 F   | *438.13 F |
| 74  | 1   |          | *MOTOR NO.1, WIPER WASHER JAR (DISC 10%) | Cracked       | 239.00 F   | *215.10 F |
| 75  | 1   |          | *MOTOR NO.2, WIPER WASHER JAR (DISC 10%) | Cracked       | 240.00 F   | *216.00 F |
| 76  | 1   |          | *SHOCK ABSORBER FRT/RH                   | Serviceable   | 394.20 F   | *- F      |
| 77  | 1   |          | *STEERING KNUCKLE RH FRT                 | Serviceable   | 580.80 F   | *- F      |

F=Franchise part.

**Total Parts (S\$)**      **27,532.86**      **6,132.81**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                  |          |                 |                 |
| 1                               | PANEL BEATING & BODYWORK.                                                        | New      | 1,264.00        | 1,000.00        |
| 2                               | SPRAY PAINT.                                                                     | New      | 2,628.00        | 1,200.00        |
| 3                               | TOWING CHARGE.                                                                   | New      | 56.00           | 40.00           |
| 4                               | TO CHECK WIRING AND SYSTEM FUNCTION.                                             | New      | 80.00           | 20.00           |
| 5                               | TO DO WHEEL ALIGNMENT / TYRE BALANCING.                                          | New      | 120.00          | 60.00           |
| 6                               | TO REMOVE AND REFIT FRT UNDER CARRIAGE.                                          | New      | 120.00          | 60.00           |
| 7                               | TO REMOVE AND REFIX ENGINE WIRE HARDNESS.                                        | New      | 200.00          | 20.00           |
| 8                               | TO TRANSFER DOOR MECHANISM.                                                      | New      | 120.00          | 0.00            |
| 9                               | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).                                 | New      | 120.00          | 20.00           |
| 10                              | TO REMOVE AND REFIT TYRE.                                                        | New      | 120.00          | 0.00            |
| 11                              | TO REPLACE SUNDRY PARTS.                                                         | New      | 100.00          | 0.00            |
| 12                              | TO WASH AND VACUUM.                                                              | New      | 60.00           | 0.00            |
| 13                              | TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER. | New      | 120.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                  |          | <b>5,108.00</b> | <b>2,420.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >