

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20005538/Aea3q2
	8 SHENTON WAY AXA TOWERSING			Date:	13/01/2021
	ATTN:JAS TAN			Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFD 86K	Veh. Inspected		SMC 3973C
	Policy No.	GA512646/1	Coverage (\$)		0.00
	Claim No.	S0M02NHG	Excess (\$)		0.00
	Assign From		Assign Date		04/05/2020
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN QASHQAI	c.c		1197
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	SJNFEAJ11U2312787	Colour		RED
	Odometer	33635 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/60 R17	BRIDGESTONE		6 mm
	L/H Front Tyre	215/60 R17	BRIDGESTONE		6 mm
	R/H Rear Tyre	215/60 R17	BRIDGESTONE		6 mm
	L/H Rear Tyre	215/60 R17	BRIDGESTONE		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/05/2020	Inspection Dat	e	04/05/2020
	Survey held at	NEW HOCK TECK MOTOR PTE	LTD		
		1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				