

REF: CS1 / LPC 20005554 / v.f3

Special Instruction:

Part By Part \$ 7409.00

From (Person): Gerald Poh

of

LPC

ASSIGNMENT (Office)

Date/Time: 5.5.2019 9.30A.M

Estimated Cost:

Bill to:

Third Parties:

Claimant: Vicom

Surveyor:

Workshop: SBS Transat

OD/TP Re-inspection Evaluation

To Inspect Vehicle No:

SBS 3149L

Insured:

YN 9365T

at Workshop m/s

SBS Transat

Tel:

62848866

of 205 Brimble Road

Policy No:

Claim No: 19119/VCO5/023331

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.12.2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time:

Confirmed with

Final Fig

days (Red \$ / %; Original 8 days)

Date/Time:

Submit Final Fig

days (Red \$ / %; Original days)

Date/Time

Action/Instruction

SBS 3149L - X

YN 9365T - X

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time

File Pass to

2) Date/Time

File Return to

3) Date/Time

File Pass to

4) Date/Time

File Return to

5) Date/Time

File Pass to

6) Date/Time

File Return to