ASS. REC. BY: Steve | REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SML 1452E Yr Regn: 7/5/19

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Shuttle Hybrid cc 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp Reading: 74734 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP72009063

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/60R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	30/4/20	D.O.I.	5/5/20

Survey held at My Car Consultant

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-79K

Date/Time, File Pass to? 1) _____

Date/Time, File Return to? 2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Survey Fee:	
Transportation:	
___S + RS, ___SI	
Photos	
Others	
TOTAL	