

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PRE-REPAIR INSPECTION REPORT

AUTO & GENERAL INSURANCE (S) PL Ref: CS3/AGI20005570/Ntf3s2

(BUDGET DIRECT INSURANCE)190 CLEMENCEAU Date: 30-09-2020

AVE #03-01SINGAPORE SHOPPING CTR S239924



Page No.:1 of 1

AVE	#03-01SINGAPOF						
			Code: AGI				
1. Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	SKM 152X	Veh. Inspected	FBP 7030J			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	C10006270/KY	Excess (\$)	0.00			
	Assign From	IVY RATILLA	Assign Date	05/05/2020			
2. Vehicle Particulars & Condition							
	Make & Model	YAMAHA XMAX 300	c.c	292			
	Engine No.	HIDDEN	Year of Reg.	2019			
	Chassis No.	MH3SH084XK006423	Colour	SILVER			
	Odometer	29346 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM			
	General	FAIR					
3. Conditions of Tyres							
		Size	Make	Balance			
	R/H Front Tyre	120/70 R15	BRIDGESTONE	3 mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre	140/70 R14	BRIDGESTONE	3 mm			
	L/H Rear Tyre			mm			
4.	4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.						
5. General Information							
	Accident Date	30/04/2020	Inspect Date / Time	08/05/2020 ( 08:32 AM )			

5.	General Information					
	Accident Date	30/04/2020	Inspect Date / Time	08/05/2020 ( 08:32 AM )		
	Survey held at	BIKE PRODUCTION PTE LTD				
		610 SERANGOON ROAD SINGAPORE 218216				

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C)ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,00-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:

3 Working Days

Report Ref No. CS3/AGI20005570/Ntf3s2

Inspected By

MUHAMMAD NAZRIL BIN ABDULLAH

1

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.