

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 May 2020		06 May 2020 13:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: XIN JIA FU FOOD PTE LTD, Co. Reg. No.: 201718107H									
Main Claimant: KHOO KWEE SIANG, ID: S1776957Z									
Vehicle Reg. No.: SMJ1556A		Date of Loss: 22/04/2020 18:00 - :59 [13 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D201873C02		Policy/Cover Note No.: DMCVSN30760019011							
Vehicle Reg. No. (Insured): GBG8988L		Policy No. (Claimant):							
		Excess: S\$450.00							
Repairer: Sau Hock Motor Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint, 568047 Ang Mo Kio - Tel: 91098638									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/05/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ1556A (SNM20D201873C02)**
[GBG8988L]

TP
KHOO KWEE SIANG
Apr 22 2020 6:00PM
[XIN JIA FU FOOD PTE LTD]
Sau Hock Motor Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Photos/Images					3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	08/05/20 09:15	General View		Load JPG	✓	
2	08/05/20 09:15	General View		Load JPG	✓	
3	08/05/20 09:15	General View		Load JPG	✓	
4	08/05/20 09:15	General View		Load JPG	✓	
5	08/05/20 09:15	General View		Load JPG	✓	
6	08/05/20 09:15	General View		Load JPG	✓	
7	08/05/20 09:15	General View		Load JPG	✓	
8	08/05/20 09:15	General View		Load JPG	✓	
9	08/05/20 09:15	General View		Load JPG	✓	
10	08/05/20 09:15	General View		Load JPG	✓	
11	08/05/20 09:15	General View		Load JPG	✓	
12	08/05/20 09:15	General View		Load JPG	✓	
13	08/05/20 09:15	General View		Load JPG	✓	
14	08/05/20 09:15	General View		Load JPG	✓	
15	08/05/20 09:15	General View		Load JPG	✓	
16	08/05/20 09:15	General View		Load JPG	✓	
17	08/05/20 09:15	General View		Load JPG	✓	
18	08/05/20 09:15	General View		Load JPG	✓	
19	08/05/20 09:15	General View		Load JPG	✓	
20	08/05/20 09:15	General View		Load JPG	✓	
21	08/05/20 09:15	General View		Load JPG	✓	
22	08/05/20 09:16	Odometer Reading		Load JPG	✓	
23	08/05/20 09:16	Chassis Number		Load JPG	✓	

Documentation					1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	06/05/20 13:44	Pre-Repair Survey		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:
☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI20005576/GQF3S2**Date:** 12/05/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30760019011
Claimant Vehicle No :	SMJ1556A	Insured Vehicle No :	GBG8988L
Date of Loss:	22/04/2020	Nature of Claim:	TP
		Claim No:	SNM20D201873C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1556A	Engine No:	G4FGKU094351
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU865274
Reg. Date:	25/02/2019 (Man. Year: 2019)	Odometer:	28126 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/05/2020	
Date Inspected:	06/05/2020 Inspected At:	Sau Hock Motor Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/12/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500.00 - \$1000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2020)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ1556A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >