



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005604/Aqf3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 19-06-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 9265Z	Veh. Inspected	SKD 8196P
Policy No.		Coverage (\$)	0.00
Claim No.	C10006280	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	06/05/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAFP32090C867512	Colour	WHITE
Odometer	187905	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/05/2020	Inspection Date	11/05/2020
Survey held at	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------