Surveyor

REF: CS/LAW20005623/Kqf3

Special Instruction:

LS $6,980.00

ASSIGNMENT (Office)

From (Person): Chee Kiong of _____ Date/Time: 05/05/2020

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant: _____

Surveyor: _____

Workshop: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLB 2366D Insured: YP 7947S

at Workshop m/s Kum Chew Motor Tel: 64536256

of 160 Sin Ming Drive #05-08 Sin Ming Autocity Singapore 575722

Policy No: _____ Claim No: 19.26452

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/10/2018

(Client's Record)

11/05/2020 @ 2pm

H.O.D. Endorsement/Date: SJE

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, ___days (Red $____/___%; Original 8 days)

Date/Time: _____ Submit Final Fig _____, ___days (Red $_____/____%; Original___days)

Date/Time	Action/Instruction
	SLB 2366D - CS/MSG18001124/Wqd3e2 DOA: 15/01/2018
	YP 7947S - X

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____