



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/TP20005635/T1yf3e2

C/O TOPLIS AND HARDING (S) PTE LTD  
133 CECIL STREET #17-01A KECK SENG TOWER  
SINGAPORE 069535

Date : 30-06-2020



ATTN : LILY KOH

Code : LPC2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                      |                       |            |
|---------------------|----------------------|-----------------------|------------|
| <b>Insured Veh.</b> | WC 3675U             | <b>Veh. Inspected</b> | SLS 5934E  |
| <b>Policy No.</b>   |                      | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | 20/20/20/LL00/003448 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | VICTOR FONG (TOPLIS) | <b>Assign Date</b>    | 08/05/2020 |

#### 2. Vehicle Particulars & Condition

|                         |                   |                     |            |
|-------------------------|-------------------|---------------------|------------|
| <b>Make &amp; Model</b> | B.M.W. X4         | <b>c.c</b>          | 1997       |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2017       |
| <b>Chassis No.</b>      | WBAXW120800V44937 | <b>Colour</b>       | WHITE      |
| <b>Odometer</b>         | 48058             | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD              |                     |            |

#### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 245/50 R18  | MICHELIN    | 6 mm           |
| <b>L/H Front Tyre</b> | 245/50 R18  | MICHELIN    | 6 mm           |
| <b>R/H Rear Tyre</b>  | 245/50 R18  | MICHELIN    | 6 mm           |
| <b>L/H Rear Tyre</b>  | 245/50 R18  | MICHELIN    | 6 mm           |

#### 4. Description of Damages

|   |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS. |
|---|

#### 5. General Information

|                       |  |                        |            |
|-----------------------|--|------------------------|------------|
| <b>Accident Date</b>  | 29/04/2020   | <b>Inspection Date</b> | 08/06/2020 |
| <b>Survey held at</b> | PERFORMANCE MOTORS LTD<br>303 ALEXANDRA ROAD<br>SINGAPORE 159941 |                        |            |

#### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

#### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>6 Working Days</b> |
|-------------------------------------|-----------------------|