



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20005648/Kea3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 03-06-2020



ATTN:RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 5553S	Veh. Inspected	SMR 5549C
Policy No.	VPA/P2246722	Coverage (\$)	0.00
Claim No.	S0M02NRM	Excess (\$)	0.00
Assign From		Assign Date	11/05/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C 180 KOMPRESSOR (A)	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2040452A681977	Colour	METALLIC BLACK
Odometer	79518	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	KUMHO	8 mm
L/H Front Tyre	225/45 R17	KUMHO	8 mm
R/H Rear Tyre	225/45 R17	KUMHO	8 mm
L/H Rear Tyre	225/45 R17	KUMHO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS

5. General Information

Accident Date	06/05/2020	Inspection Date	11/05/2020
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------