

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4 / FC120005678/46a3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLV 6421X

at Workshop m/s

Tony Automotive.

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

23K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

2

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

LTA 15018

Date / Time

Action / Instruction

not 7982

steering rack already bent / Jammed.

coe 3-1-2025 but 4 yrs. later.

1/5 @ 6100 confirmed with Tony

Veh No:

SLV 6421X

Yr Regn:

1110

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Hyundai Avante

c.c

1591

Colour

maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

139835

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMFIDU41BMA4933699

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fin 29

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/5/20

D.O.I.

13/5/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Lh. 015 Body &

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

*not Authorized
khk*

13/12/20

2/5 @ 6100

6 days. To be paid after 6 days

4/5 @ 6100

Model : Hyundai Avante

Veh No: SLV6421X

Qty

List Items

Amount S\$

1	FRONT RIGHT FENDER	
1	FRONT RIGHT INNER COWLING	
1	FRONT STEERING RACK	
1	FRONT DRIVE SHAFT	
1	FRONT RIGHT SUSPENSION ASSY	422.30
1	FRONT RIGHT LOWER ARM	
1	FRONT RIGHT KNUCKLE	425.50
1	FRONT RIGHT WHEEL HUB BEARING ASSY	183.90
1	FRONT RIGHT WHEEL HUB ASSY	
1	FRONT RIGHT MEMBER ASSY	
1	FRONT RIGHT DOOR	966.20
1	FRONT RIGHT DOOR: Sticker	
1	FRONT RIGHT DOOR CHECKER	
1	FRONT RIGHT DOOR UPPER HINGE	
1	FRONT RIGHT DOOR LOWER HINGE	
1	FRONT RIGHT DOOR WEATHER STRIP	133.50
1	FRONT RIGHT BODY WEATHER STRIP	
1	FRONT RIGHT DOOR LATCH ASSY	
1	FRONT RIGHT DOOR MODULE	
1	FRONT RIGHT DOOR SCUFF	
1	FRONT RIGHT ROCKER PANEL	
1	FRONT RIGHT DOOR POWER MOTOR	

<i>Surf</i>	956.2	<i>X</i>
<i>Surf</i>	273.5	<i>X</i>
<i>Surf</i>	1913.6	<i>✓</i>
<i>Surf</i>	918.3	<i>✓</i>
<i>Surf</i>	827.6	<i>✓</i>
<i>Surf</i>	330.2	<i>✓</i>
<i>Surf</i>	463.8	<i>✓</i>
<i>Surf</i>	250.6	<i>✓</i>
<i>Surf</i>	280.5	<i>✓</i>
<i>Surf</i>	1514.8	<i>X</i>
<i>Body</i>	1670.5	<i>✓</i>
<i>Surf</i>	30.4	<i>✓</i>
<i>Surf</i>	82.2	<i>X</i>
<i>Surf</i>	66.1	<i>X</i>
<i>Surf</i>	66.1	<i>X</i>
<i>Surf</i>	156.2	<i>✓</i>
<i>Surf</i>	139.5	<i>X</i>
<i>Surf</i>	387.2	<i>X</i>
<i>Surf</i>	380.4	<i>X</i>
<i>Surf</i>	86	<i>✓</i>
<i>Surf</i>	783.2	<i>✓</i>
<i>Surf</i>	650.5	<i>✓</i>

Parts Total 12227.4

Less 20% 2445.48

9781.92

Special Nett Items

Qty

List Items

Amount S\$

1	FRONT RIGHT SPORTS RIM
---	------------------------

<i>no / Surf</i>	551.2	<i>350 s. w</i>
Sub Total	551.2	

Qty

Labour charges

1	REMOVE AND INSTALL DOOR POWER MOTOR
1	REMOVE AND INSTALL RH WHEEL ASSY
1	CHECK WHEEL ALIGNMENT
1	TUFFKOTE
1	SPRAY PAINTING
1	PANEL BEATING, GENERAL INSTALLATION ETC.

	300	<i>60</i>
<i>11</i>	600	<i>X</i>
	120	<i>60</i>
	150	<i>60</i>
	1000	<i>700</i>
	1200	<i>600</i>
Sub Total	3370	

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

13703.12



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

SUPPLEMENTARY

Model : Hyundai Avante

Qty List Items

1 FRONT RIGHT ROCKER PANEL OUTER GARNISH
1 FRONT RIGHT DOOR TRIM BOARD *645.30*

Veh No: SLV6421X

Amount S\$

NS 386.6 *X*
Return 1150.5
Parts Total 1537.1
Less 20% 307.42
1229.68

Special Nett Items

Qty List Items

1 SET DOOR PANEL CLIPS

Amount S\$
1 1 60 *X*
Sub Total 60

Qty Labour charges

1 REMOVE AND INSTALL *front under carriage*

800 *350*
Sub Total 800

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$ 2089.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6851.10
20%
P-5480.88
S.N-350.00
A-1830.00
7660.88
20%
6128.70