

ASS. REC. BY:

REF:

AIG / 200056861KB

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

1.30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STV 1914 Yr Regn: 06, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M. C43 AMG c.c. 2996Colour: White A/C: Insured / Std / NI / NASp. Reading: 21282 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2050642R 329836

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: Pir 225/40R19Continental 255/35ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 8/15/20

Survey held at

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 19/5/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/6 87660.13 Car hire

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Date: 12.05.2020
 Vehicle No: SJV191Y
 Model: MERCEDES BENZ C43 AMG
 Chassis: WDD2050642R329836-2017
 Reg.Year: 2018

Third Party Insurer: AIG
 Third Party Veh No: GBJ7584J
 Date of Accident: 08.05.2020

07660.13
 ESTIMATE

NOT AUTHORIZED
 Resurvey B & paint 4 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER 1720	1	my car	\$1,910.00
2	FRONT BUMPER CLIPS	12	\$6.50	\$78.00
3	FRONT BUMPER SIDE RETAINER RH	1	CM	\$52.00
4	FRONT BUMPER INNER GUIDE RH	1	Sn	\$90.00
5	FRONT BUMPER REINFORCEMENT	1	R	\$470.00
6	FRONT FENDER RH 980	1	R	\$995.00
7	FRONT FENDER EMBLEM RH	1	me	\$222.00
8	FRONT SUPPORT PANEL TIE BAR	1	DiT	\$363.00
9	FRONT FENDER INNER LINER RH	1	CM	\$270.00
10	FRONT FENDER INNER LINER CLIPS RH	10	\$5.50	\$55.00
11	FRONT HEADLAMP ASSY RH 3150	1	my CM	\$3,505.00
12	FRONT HEADLAMP LOWER BRACKET RH	1	R	\$120.00
13	FRONT BUMPER LOWER LIP GARNISH COVER RH	1	my CM	\$305.00
14	FRONT BONNET	1		REPAIR
SUB TOTAL				\$8,435.00
LESS 10%				-\$843.50
PARTS TOTAL				\$7,591.50

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.

600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT BONNET, FRONT FENDER RH & ETC.

800.00

LABOUR CHARGES TO REMOVE, REFIX & REPAIR FRONT PARKING SENSOR & ETC. TO EFFECT REPLACE OF FRONT BUMPER.

120.00

TO DIAGNOSIS FAULTY CODE & RESET MEMORY

150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,670.00

TOTAL \$9,261.50

TingAn

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 23.06.2020
Vehicle No: SJV191Y
Model: MERCEDES BENZ C43 AMG
Chassis: WDD2050642R329836-2017
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: GBJ7584J
Date of Accident: 08.05.2020

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER REINFORCEMENT SUPPORT BRACKET RH	1		<i>Box</i> \$82.92 ✓
			SUB TOTAL	\$82.92
			LESS 10%	-\$8.29
			PARTS TOTAL	\$74.63 ✓