

ASS. REC. BY: JamesREP: CS/EG/20005702/R1/3

8716

COE: 2021/DEC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SL3 1011S  
at Workshop m/s MOVA  
of 1008, BUKIT MEKAY LN # 01-04  
Insured: EG1  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Sal. or Market Value: 62K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SL3 1011S Page: 2011 DEC  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 730Li ATABS CO 2916  
Colour: BLACK Air Insured / Std / NI / NA  
Sp. Reading: 173386 TIR Audio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA KB22060C94181Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18  
R: 245/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /  
TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm P Bal. 6 mm  
L/Bal. 6 mm L Bal. 6 mm  
D.O.A. 10/05/2020 D.O.L. 18/05/2020

Survey held at MOVA (CBM)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PART BY PART \$4066.56, 4DAYS (RED: 481.92; 10%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

1) \_\_\_\_\_

2) \_\_\_\_\_

Rep. Formed:

Long Term / B.C.C.

PART BY PART \$4066.56

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$1

Photos

where

Total

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane 3,**  
**#01-04/06/08. Singapore 159722**

**Insurer Reference:**  
**Repairer Reference: CK138236**  
**Date calculated: 13/05/2020 9:56 AM**

**Full Report**  
**Registration: SLJ1011S**  
**Printed: 13/05/2020 9:56 AM**

### **Summary Information**

---

#### **Claim**

Location:	Singapore (SG)	Work Provider:	ERGO Insurance Pte Ltd
Printed by:	GOH CHAI HOCK	Currency:	SGD
Claim Reference:		Date of Incident:	10/05/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### **Vehicle Details**

---

#### **Vehicle**

Manufacturer:	BMW
Model:	7-SERIES F01/02
Sub Model:	730 LI
Model Sheet Number:	01 06 16
Registration:	SLJ1011S
VIN number:	WBAKB22060C951181
Odometer:	

#### **Model Specs**

FROM 03/2011	INTER LIGHT AMBIENCE	AIR CON AUTO 4-ZONES	DVD CHANGER
DIP/FOLD MIRROR	NAVIG-SYST PROFESS	HI-FI SPEAKER SYSTEM	COMFORT ACCESS SYST
AUTO TAILGATE CONTR	SOFT CLOSE AUTOMATIC	DAKOTA LEATHER TRIM	LUMBAR SUPPORT
FRONT COMFORT SEATS	SIDE ROLLER BLIND	REARVIEW CAMERA	NOBLE WOOD FINELINE
PARK DISTANCE CONT	3.0 LTR 190 KW	O2 VOLUME	INTEGRAL ACTIVE STRG
TYRES 245/50 WR 18	WHEELS 8J X 18 ALLOY	ELECTRIC SUNROOF	TWO COAT METALLIC
PREPARE OFF VEHICLE			

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

Code	Description	Time Base 12 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.50
NO NUMBER	R + R REAR CENTRE FLOOR PANEL COVER		2.0	7.50
51 12 656	R + R REAR BUMPER		8.0	30.00
51 12 552	R + R REAR BUMPER CARRIER (BUMPER REMOVED)		5.0	18.75
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)		1.0	3.75
51 12 825	R + R RR CTR BUMPER GUIDE		3.0	11.25
66 20 603	ADD/WORK PARK DISTANCE CONTROL		3.0	11.25
51 49 500	R + R TAILGATE TRIM		3.0	11.25
51 13 900)	R + R TAILGATE COVER		2.0	7.50
NO NUMBER	R + R REAR WIRING HARNESS		12.0	45.00
9852	FAULT MEM AFTER REP READ OUT		20.0*	75.00
2711	REAR PANEL REPAIR		20.0*	75.00
2987	TAILGATE TRIM REPAIR		5.0*	18.75
2611	L/R REFLECTOR CHECK			
2612	R/R REFLECTOR CHECK			
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>7.20</b>	<b>86.0</b>	<b>322.50</b>
<b>Total of Labour</b>				<b>322.50</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		14.0	

## Paint Work

## SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR BUMPER TRIM NEW PART PAINT K1R	5.0	
	REAR PANEL REPAIR PAINTING <50%	10.0	
	TAILGATE TRIM REPAIR PAINT PLASTIC	10.0	

## Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	70.36
2603	REAR BUMPER TRIM NEW PART PAINT K1R	12.30
2711	REAR PANEL REPAIR PAINTING <50%	9.37
2987	TAILGATE TRIM REPAIR PAINT PLASTIC	12.15

## Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		39.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
<b>Total</b>	<b>10 WU/h</b>	<b>72.0</b>	<b>324.00</b>
<b>Total</b>	<b>12 WU/h</b>	<b>7.20</b>	<b>86.4</b>
			<b>324.00</b>

## Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	82.66
Repair Painting	9.37
Repair Painting Plastic	12.15
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
<b>Total</b>	<b>145.48</b>

## Spare Parts

prices as at 2020-04-13

Code	Description	Part Number	Price SGD
2669	L/INN U-SONIC SENDER	66 20 2 180 495 Original <i>Am</i>	200.00
2670	R/INN U-SONIC SENDER	66 20 2 180 495 Original <i>Am</i>	200.00
2625	REAR BUMPER ADAPTER	51 12 7 186 826 Original <i>? cra</i>	155.00
2643	REAR BUMPER CARRIER	51 12 7 183 884 Original <i>? bent</i>	600.00
2583	REAR BUMPER COVER	51 12 7 209 926 Original <i>era</i>	1,400.00
2650	REAR BUMPER MNTG KIT USE SINGLE PARTS	Original <i>neu</i>	30.00
2603	REAR BUMPER TRIM	51 12 7 209 918 Original <i>R</i>	280.00
4267	REAR CTR FLOOR COVER	51 75 7 187 958 Original <i>cra</i>	250.00
9603	REAR HARNESS	61 11 9 326 077 Original <i>? xsvc</i>	180.00
2623	RR BUMPER CTR GUIDE	51 12 7 301 225 Original <i>? cra</i>	120.00
f: OEM Parts	<b>Savings</b>		<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>		<b>3,415.00</b>
u: Used parts	<b>Addition(+10.00%)</b>		<b>341.50</b>
	<b>Total</b>		<b>3,756.50</b>

## Final Calculation

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	3,415.00	
<b>Total Parts</b>	341.50	<b>3,756.50</b>
<b>Labour Time Base 12 WU/h</b>		
Total 86.0 WU X 45.00 SGD/h	326.25	322.50
<b>Total of Labour</b>		<b>322.50</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 72.0 WU X 45.00 SGD/h	346.50	324.00
Material Cost	143.31	145.48
<b>Total Paint Including Material</b>		<b>469.48</b>
<b>Repair Cost Excludes GST</b>		<b>4,548.48</b>
GST (+7.00%)		<b>318.39</b>
<b>Repair Cost Included GST</b>		<b>4,866.87</b>

## Comments

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue  
Hp 9001068  
4 days  
P/P  
18/05/2020 @ 1045  
Resy before paint

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/05/2020 17:07
Date Of Accident	10/05/2020 17:50
Exact Location Of Accident	ALONG QUEENSWAY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ1011S
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	YEAP KOK LIM
NRIC No	SXXXX871E
Email Address	ALAN@N-QUANTUM.COM
Mobile Phone No	(LOCAL) +65-82281388
Alternative Phone No	OTHERS-NOPHONE

#### Vehicle Particulars

Manufacturer	BMW
Model	730LI AT ABS D/AB 2WD 4DR NAV HID SR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5085687864
Cover Note Number	

#### Driver

Name of Driver	YEAP KOK LIM
NRIC No	SXXXX871E
Date Of Birth	10/01/1970
Occupation	INDOOR
Date Of Driving Pass	05/12/1995
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82281388
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	ALAN@N-QUANTUM.COM

Address	220 DEPOT ROAD #17-76
Postcode	109704
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZING
Road Surface	WET

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : AUDREY YEAP YI TING GENDER: : FEMALE
Passenger 2	NAME: : YANG JING GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number	SKN4851E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUN JUN KAI MARC
NRIC/Passport Number	SXXXX494I
Contact Number	
Address	
Postcode	

Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



LICENSE PLATE: SLJ1011S  
 CONTACT NUMBER: 82281388  
 LOCATION: Along Queensway  
 ACCIDENT DATE & TIME: 10 MAY 2020 / Around 5:50pm  
 E-MAIL ADDRESS: alan@n-quantum.com

My's car stopped at traffic light. Vehicle plate SKN4851E hit my's car from behind.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

Please state:

☐ Claim Own Policy   
 ☒ Claim Third Party   
 ☐ Claim OD/TP at other workshop   
 ☐ Reporting Only

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I Chua Jun Kai MARC  
(Cchai Junkai) car owner of  
SKN4851E hit car number  
SLJ1011S from behind. Around  
5:50pm 10 May 2020.

I fully agreed is my fault  
and will responsible for the  
accident.

J/K Munter  
S870P4941

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	871E
Vehicle No.:	SLJ10115
Vehicle to be Exported:	No
Intended Deregistration Date:	18 May 2020
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	13607829N52B30AF
Chassis No.:	WBAKB22060C951181
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$73,789.00
Original Registration Date:	09 Dec 2011
First Registration Date:	09 Dec 2011
Transfer Count:	2
Actual ARF Paid:	\$73,789.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2021
PARF Rebate Amount:	\$40,583.00

COE Expiry Date:	08 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$77,340.00
COE Rebate Amount:	\$12,025.00
Total Rebate Amount:	\$52,608.00

The information contained herein is correct as at 18 May 2020


OK

09 Dec 2011



## ► BMW 7 Series 730Li Sunroof

[Home](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



Location Map



**Price** \$62,000

**Depreciation** \$16,210 /yr  
View models with similar depre

**Reg Data** 09-Dec-2011  
(1yr 6mths 20days COE left)

**Mileage** 109,000 km (12.9k /yr)

**Manufactured** 2011

**Road Tax** \$2,382 /yr

**Transmission** Auto

**Derog Value** \$51,678 as of today (change)

**OMV** \$73,453

**COE** \$72,350

**ARF** \$73,453

**Engine Cap** 2,996 cc

**Power** 190.0 kW (254 bhp)

**Curb Weight** 1,855 kg

**No. of Owners** 3

**Type of Vehicle** Luxury Sedan

### Features

6 Cylinder Inline, 6 Speed Auto Transmission, 254bhp, Torque: 310Nm. View specs of the BMW 7 Series (2009-2012)

### Accessories

Multi Function Steering Wheel, Keyless System, Cruise Control, Bluetooth Interface, Navigation, Auto Climate Control Aircon.

### Description

Good Condition, Well Maintained, New Tyres, New Interior Leather, More Than Enough Leg Room For Passengers. Consignment Unit, Trade In Welcome, Loan And Insurance Available, Call Now For Viewing Appointment.

### Category

Premium Car

### Status

Available


### Resources



Car ValueCheck - Free  
Find out the market value of your existing car for free.



Vehicle Identification  
Required to have this car inspected professionally



STC Now a 24 hr 7 day 24 hr used cars site on 011-867972801-2543

72K

70K

68K

66K

64K

62K

60K

58K

56K

Premium Motoring



9 Tagore Lane #02-07

101 Tagore

Tel: 66028048

630-0000