

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB1503U
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2020
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Primary Colour:	Multicolor
Manufacturing Year:	2014
Engine No.:	50338180213822
Chassis No.:	WMAA22ZZ4E7002265
Maximum Power Output:	-
Open Market Value:	\$255,457.00
Original Registration Date:	20 Oct 2014
First Registration Date:	20 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 13 May 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/05/2020 14:38
Date Of Accident	08/05/2020 17:05
Exact Location Of Accident	BUKIT TIMAH ROAD AFTER BS:40041 (NEWTON STATION EX
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1503U
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	1XXXXX292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN NL320F (A22)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken:	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095488MFBP
Cover Note Number	

Driver

Name of Driver	TAN BOON KENG
NRIC No	SXXXX704I
Date Of Birth	05/08/1958
Occupation	OUTDOOR
Date Of Driving Pass	31/01/1980
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 5

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

On 08/05/2020 at 1703 hrs, I was driving SMB1503U, Svc 171. I was driving on the left most lane at a speed of 30 km/h with about 5 pax onboard. While I was driving, a car overtook me on the right and suddenly, grazed against the right side of my bus. It did not stop initially. However, after I had horned at it, it came to a stop and I stopped behind it. I alighted to check on the bus. There were scratch marks on the right side of my bus while the car suffered damages to its left side. There were no injuries. That's all.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ6122A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver CHAN WAI MENG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

X

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

A: SMB15034.

B: SKZ 612A

SKETCH PLAN

Bulld Terrier (grey)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Bukit Timah Road after BS:40041
(Newton station Exit C)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT: (NEWTON STATION EXIT C)

DECLARATION

DECLARATION
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

© 1998 Blackwell Science Ltd, *Journal of Internal Medicine* 243: 399–406

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NRIC/FIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Hoxsey Industrial Park E4, Singapore 157105
FAX Number 4344444
Estimated Telephone Number 68642622
Accident Reporting Number 68642672


Date Generated : 13/05/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1503U
Case Reference Number	BUS/05/20/1006
Registration Date	20/10/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Tan Boon Keng
Type of Accident	Side Swipe
Accident Date and Time	8/5/2020 5:03 PM
Accident Reported Date and Time	12/5/2020 11:31 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1503U-RIGHT FRONT PORTION SKZ6122A (TP) INSURED WITH
Prepared Date and Time	12/5/2020 1:16 PM
Chassis Number	WMAA22ZZ4E7002265
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$1,805.76	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,573.76	\$0.00
Lump Sum Total	\$3,550.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	12/05/2020 1:24 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
No. 11, Hsinchu Road, Part 5A, Singapore 157105	
Fax Number: 65666662	
Estimator Telephone Number: 65666663	
Accident Reporting Number: 65662672	

Date Generated: 13/05/2020

User ID: BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,060.00	570.
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	616.
Total Spray Painting & Panel Beating	\$708.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009965	BODY RH	A01001-CW570	PANEL, SIDE:R4 WITH FRAME, FOR MAN A22 BUS	1.00	\$499.70	100.00	\$0.00	Repair	XK
6010152	Body	F01001-CW266	COVER, HEADLAMP: FRT, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Xh
6010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	?
6010307	VE	81.25320-6112	FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	?
Total					\$3,982.40		\$2,257.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days
L/S.
After paint photo.
Run Pm (Lkk)
13/05/2020
TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: