

ASS. REC. BY:

REF:

C44/EQ120005706/ea3

1793

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMP 3573E

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA RD

Insured: EQ1

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 132K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMP 3573E

Yr Regn:

2019 / SEP

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X1 SDRIVE 18i c.c 1499

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

10710

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAJH120605N75254

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

09/05/2020

D.O.I.

22/06/2020

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time / Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format:

Lump Sum / L.B.H. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Ty	Singapore NRIC
Owner ID:	179J

Vehicle No.:	SMP3573E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jun 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I LED NAV
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	37375655B38B15A
Chassis No.:	WBAJG120605N75254
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$35,726.00
Original Registration Date:	24 Sep 2019
First Registration Date:	24 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$42,017.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Sep 2029
PARF Rebate Amount:	\$31,512.00

COE Expiry Date:	23 Sep 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$34,235.00
Total Rebate Amount:	\$65,747.00

The information contained herein is correct as at 22 Jun 2020

OK



Used 2019 BMW X1 sDrive18i for



Merimen e-Claims



PART/CO

rt.com/used_cars/info.php?ID=906145&DL=2351

▶ BMW X1 sDrive18i

Overview

Financial

Accessories

Similar

Research

Photos

Map



PERFORMANCE PREMIUM SELECTION LIMITED

Price \$133,800

Depreciation  \$12,190 /yr
View models with similar depreReg Date 24-Oct-2019
(9yrs 4mths 1day COE left)

Mileage 2,600 km

Manufactured  2019Road Tax  \$684 /yr

Transmission Auto

Dereg Value  \$67,309 as of today (change)OMV  \$34,226COE  \$40,001ARF  \$39,917

Engine Cap 1,499 cc

Power 103.0 kW (138 bhp)

Curb Weight  1,430 kgNo. of Owners  1

Type of Vehicle SUV

Features

BMW TwinPower Turbo 3 Cylinder Engine With 140bhp, 220Nm Of Torque. 0-100km/h In 9.7s, Top Speed 200km/h, 7 Speed Transmission DCT, Front Wheel Drive. View specs of the BMW X1 (2015)

Compare 