

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



11.05.2020

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55107
Date Estimated : 11/05/2020
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ang Peng Seong (Hong Mingxiong)
654 Senja Road
#20-258

Singapore 670654

- ACCOUNT - 45912
EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP3573E	WBAJG120605N75254	24/09/2019	X1 sDrive18i	0

DESCRIPTION

To replace bumper rear cover and boot lid

1700 2,550.00

To spray paint bumper rear cover and boot lid

1805 2,006.00

To remove and install rear windscreen glass

574.00

To conduct water leak tests.

75.00

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function.

561? 661.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

? 150.00

Total Labour 1: 6,488.00

DESCRIPTION

BLIND RIVET NUT M6 *see*

QTY	PRIC	VALUE
4	2.70	10.80

BOOTLID *51*

1	1,236.65	1,236.65
---	----------	----------

RR BUMPER CARRIER ?

1	496.35	496.35
---	--------	--------

MOUNTING SMART OPENER

1	45.55	45.55
---	-------	-------

RR BUMPER LH CORNER MOUNTING ?

1	142.65	142.65
---	--------	--------

RR BUMPER RH CORNER MOUNTING ?

1	142.65	142.65
---	--------	--------

REAR BUMPER PANEL PRIMED *de*

1	903.40	903.40
---	--------	--------

REAR BUMPER MIDDLE TRIM PANEL (PDC) *see*

1	265.65	265.65
---	--------	--------

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55107
Date Estimated : 11/05/2020
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP3573E	WBAJG120605N75254	24/09/2019	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
EMBLEM GROMMET <i>see ✓</i>	2	0.85	1.70
BMW PLAQUE WITH ADHESIVE FILM <i>see ✓</i>	1	71.60	71.60
LETTERING S DRIVE 18i <i>see ✓</i>	1	96.65	96.65
LETTERING X1 <i>see ✓</i>	1	64.45	64.45
LOCK TRUNK LID ?	1	229.10	229.10
BOOT LID/TAILOATE PUSH BOTTON ICAM ?	1	48.65	48.65
Lock plate ?	1	12.40	12.40
SENSOR WIRE FOR SMART OPENER TOP ?	1	46.30	46.30
SENSOR WIRE FOR SMART OPENER BOTTOM ?	1	50.90	50.90
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>see ✓</i>	2	131.55	263.10

Total Parts : 4,128.55

Claims OD <u>3rd Party</u> Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>22/06/2020 @ 1100</u>	Excess S\$ _____
Surveyor's Name <u>RYSUL</u>	Sign _____
Surveyor's Tel <u>9000 68</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>PHIL</u> Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>4-5 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	6,488.00
Parts	:	4,128.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	743.16
Grand Total	:	11,359.71

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **