

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20005734/Uga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Date: 17-07-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJE 902C	Veh. Inspected	SGL 1188P	
	Policy No.	GA539960/1	Coverage (\$)	0.00	
	Claim No.	S0M02NYA	Excess (\$)	0.00	
	Assign From		Assign Date	14/05/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PICNIC (A)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	JTEGH23B000023354	Colour	SILVER	
	Odometer	165972	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	FALKEN	6 mm	
	L/H Front Tyre	205/60 R16	FALKEN	6 mm	
	R/H Rear Tyre	205/60 R16	FALKEN	6 mm	
	L/H Rear Tyre	205/60 R16	FALKEN	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/05/2020	Inspection Date	14/05/2020	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			