

ASS. REC. BY:

REF: CS/MSG20005739/Eqf3

Special Instruction:

Surveyor: STEVE

ASSIGNMENT (Office)

From (Person): Jasmine Lok of MSIG Date/Time: 14 May 2020 13:51

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFX 8336G Insured: SJH 6484L

at Workshop m/s Car Pro Auto Tel: 9750 6777

of Blk 6 Yew Tee Industrial Estate 399-J, Woodlands Road

Policy No: A29130267TMC Claim No: 623996

Sum Insured: Excess:

Make of Veh: D.O.A. 12/05/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 14-5-20 3.21P.M Person Contacted: TING WEI Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SFX 8336G - X
	SJH 6484L - X

18/05/20@10am INFORMED JASMINE LOK, WE ARE PENDING FOR ESTIMATE FROM REPAIRER.

20/05/20@11.09am REVISED TO JASMINE LOK VIA MERIMEN.

Steve finalised LS \$5150, 7 days (Red \$8205.75, 61%)