

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 14.05.2020

Time: 09:06:33

Page: 1/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305399123
 REGN NO : SHC8797X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.03.2016
 DATE/TIME IN : 13.05.2020 16:35
 ACCIDENT DATE : 13.05.2020

China Taiping
 (LKS) LKK - Ram

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0576-G	REAR FENDER LH	1	2,171.40 20.00 1,737.12
0002	28-01-9999-2023-A	REAR DOOR APPS LH	1	80.00 80.00
0003	04-01-0103-0745-G	REAR WINDSCREEN MOULDING	1	51.80 20.00 41.44
0004	05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC	2	92.00 92.00

SUB-TOTAL : 1,950.56

JOB NATURE

0000 PB	PANEL BEATING (RLH DOOR) + (Fender)	600.00	\$560
0001 SP	SPRAYPAINT CHARGE	500.00	\$400
0002 20-00	TUFF COAT ON AFFECTED PARTS.	80.00	xnn
0003 L	R/I REAR WINDSCREEN GLASS	150.00	\$100
0004 L	R/I UPHOLSTERY ETC	150.00	\$80

SUB-TOTAL : 1,480.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram LKK
 14/05/2020 11:30
 Ram Suram@lkkauto.com
 88622728
 add repair photo
 3 repair days

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.05.2020

REPAIR ESTIMATE

Time: 09:06:33

Page: 2/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305399123
REGN NO : SHC8797X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.03.2016
DATE/TIME IN : 13.05.2020 16:35
ACCIDENT DATE : 13.05.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,430.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 14.05.2020 08:27

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:


JC NO305399123

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO: SHC8797X	MILEAGE
IS OWNER NO ADDRESS	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 13.05.2020 16:35
	YR OF MANU. 17.03.2016	TARGET DATE
DUPLICATE CARD NO.	CHASSIS CODE KMHLB41UMGU085786	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 13.05.2020
NATURE: 3P 13.05.2020

/NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Check-out Slip

Exit Pass

No.: SHC8797X

JUMANI

Vehicle No.: SHC8797X

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard