JY

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE (China Taiping CLS) LKK - Ram

Date: 14.05.2020
Time: 09:06:33
Page: 1/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305399123
REGN NO	:	SHC8797X
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	I-40
DATE OF REGN	:	17.03.2016
DATE/TIME IN	:	13.05.2020 16:35
ACCIDENT DATE	:	13.05.2020

JOB / PARTS DESCRIPTION	QTY	IND UNIT-PRICE	DISC%	AMOUNT	
PART REQUISITION					
0001 04-01-0103-0576-G REAR FENDER LH	1	2,171.40	20.00	1,737.12	BUC/cut
0002 28-01-9999-2023-A REAR DOOR APPS LH	1	80.00		80.00	nec
0003 04-01-0103-0745-G REAR WINDSCREEN MOULDING	1	51.80	20.00	41.44	nec
0004 05-01-0199-0032-A WINDSCREEN AHESIVE-310MLC	2	92.00		92.00	nec
			SUB-TOTAL :	1,950.56	
JOB NATURE					
0000 PB PANEL BEATING (RLH DOOR) + (Fender)				600.00	$560
0001 SP SPRAYPAINT CHARGE				500.00	$400
0002 20-00 TUFF COAT ON AFFECTED PARTS.				80.00	[redacted] xnn
0003 L R/I REAR WINDSCREEN GLASS				150.00	$100
0004 L R/I UPHOLSTERY ETC				150.00	$80
			SUB-TOTAL :	1,480.00	

LKK Auto Consultants hence notify the Repairer of the following:
- **To re**survey before/after sp ay painting
- **To dis**play damaged part s during resurvey
- **Parts** prices are subject to confirmation
- **Third party** survey is on "Without Prejudice" basis
- **No illegal** modificatio s allowed
- **Supplementary** item s ust be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram LKK
14/05/2020 1130
parasuram@lkkauto.com
88622778

(LS) add repair photo
(3) repair days

JY

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.05.2020
Time: 09:06:33
Page: 2/2

REPAIR ESTIMATE China Taiping (CLS) LKK -Ram

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305399123
REGN NO	:	SHC8797X
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	I-40
DATE OF REGN	:	17.03.2016
DATE/TIME IN	:	13.05.2020 16:35
ACCIDENT DATE	:	13.05.2020

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,430.56

AUTHORISED : YES / NO

LIMFS

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 14.05.2020 08:27 Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: JC NO305399123

'OMER

IS COMFORT TRANSPORTATION PTE LTD
'OMER NO. 7010045
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO.: SHC8797X	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 13.05.2020 16:35
YR OF MANU. 17.03.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU085786	COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 13.05.2020
ATURE: 3P 13.05.2020

/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

lo.: SHC8797X JUMANI

Service Advisor Signature/Date

urned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC8797X

Name of Service Advisor Date

To be kept by Security Guard