

CC4/III 20005764/Dea³

CDB Dec 2029

Veh No: FBE 1840 K Yr Regn: Dec / 2009

Type: M.Car / ~~M.Cycle~~ / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Spark 135 C.C 135

Colour Green A/C: Insured / Std / NI / NA

Sp. Reading N.A. T/Radio: Insured / Std / NI / NA

Eng/No: 5TP301851

C/No: 5YP 301851

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

N/S	O/S	

Tyre Size: F: 70/95 R17

R: 90/80 517

Front

Rear

R/Bal. 2 mm

R/Bal. 2 mm

L/Bal. mm

L/Bal. mm

D.O.A. 30/03/2020

D.O.I. 15/05/2020

Survey held at SG 98 Mtn Amc

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

0/s Ren y N/8 Bront

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐: Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

) Others

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.B. (\$)

Add Fee: ☐ : Site Insp (\$

☐: Interview (\$

	Tech. Invs (\$
--	----------------

: Weekend (\$)