

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 18 May 2020

ASSESSMENT FOR REPAIR: YAMAHA GDR155A (AEROX) - FBQ8256M

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard rear cover	\$75.00 ✓ CRK
1 pc	Front mudguard	\$95.00 ✓ CRK
1 pc	Wheel axle	\$60.00 X SVL
1 pc	Brake disk	\$185.00 X SVL
1 pc	Right fork assy	\$420.00 ?
1 pc	Left fork assy	\$420.00 ?
1 pc	Steering stem	\$220.00 ?
2 pcs	Steering stem bearings @ \$45.00	\$90.00 ?
1 pc	Centre cover inner body	\$120.00 ?
1 pc	Centre cover lower.	\$140.00 ?
1 pc	Front cover	\$95.00 ✓ CRK ?
1 pc	Headlamp lower cover	\$75.00 ?
1 pc	Left front fairing	\$150.00 ?
1 pc	Left front fairing emblems	\$35.00 ?
1 pc	Right front fairing	\$150.00 ?
1 pc	Right front fairing emblems	\$35.00 ?
1 pc	Top cover front	\$95.00 ✓ SVL
1 pc	Top cover front emblem	\$20.00 ✓ SVL
1 pc	Top cover rear	\$85.00 ?
		<hr/>
		\$2,565.00
	Less discount 10%	\$256.50
		<hr/>
		\$2,308.50
	<u>Special nett items</u>	
1 pc	Front sport rim	\$420.00 ?
1)	Towing charges	\$100.00 X
	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 300
2)	To remove, replace and balance front wheel rim	\$120.00 ✓ CRK ?
3)	To knock, straighten chassis & body	\$380.00 50
4)	balancing	

5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 ?
6)	Spray painting	\$300.00 100
Total Estimate		<u>\$4,508.50</u>

Note: The above estimate is subjected to the prevailing GST of 7%

NAR LKK

20/5/2020 9500

LIS

3 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: