

(08/11/13)

REF:

Surveyor: RAM**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 3362U Yr Regn: 21/07/2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai i40 c.c. 1685Colour: blue A/C: Insured / Std / NI / NASp. Reading: 476418 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLBA1UMGV092209Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WESTLAK

Front

Rear

R/Bal. 6 mm R/Bal. 7 mmL/Bal. 6 mm L/Bal. 7 mmD.O.A. 17/05/2020 D.O.I. 17/05/2020Survey held at comfort delgo (Loyang)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

AG

LS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD3362U
Vehicle to be Exported:	No
Intended Deregistration Date:	19 May 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	D4FDGU659998
Chassis No.:	KMHLB41UMGU092209
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,823.00
Original Registration Date:	21 Jul 2016
First Registration Date:	21 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$18,823.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2024
PARF Rebate Amount:	\$14,117.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,616.00
COE Rebate Amount:	\$20,646.00
Total Rebate Amount:	\$34,763.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 May 2020

OK