

W Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64795601 (AfterSales)
64796624 (Motorrad)



Due 11/6/2020
22/5/2020

GST REG. NO : M2 - 0020081 - X

14 MAY 2020

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 55114
Date Estimated : 14/05/2020
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -

Lim Choon Beng
77 Marine Drive
#03-42

Singapore 440077

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFR8370M	WBATR92030LE25585	27/07/2018	X3 xDrive30i	0

DESCRIPTION

Replace front bumper ,bonnet include remove attachment etc

Spray painting front bonnet and front bumper

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

To replace left headlight.

To carry out body cavity preservation.
(Per panel).

Sundries.

VALUE
1700 2,125.00

2102 2,336.00

150 177.00

408 481.00

100 118.00

? 150.00

Total Labour 1: 5,387.00

DESCRIPTION

BONNET cut / ? x na
LH GUIDE BUMPER ? x na
RH GUIDE BUMPER ? x na
FRT BUMPER LH INSERT ? x na
FRT BUMPER RH INSERT ? x na
FRT BUMPER PANEL PRIMED (M/CAM) repair
LH SIDE GRILLE OPEN ? x na
LH HEADLIGHT LED AHL HIGH (ICON LIG & cut
Ultraschallw
DECOUPING RING PDC TORQUE CONVERTER ? x na

QTY	PRIC	VALUE
1	1,829.55	1,829.55
1	36.80	36.80
1	36.80	36.80
1	49.90	49.90
1	49.90	49.90
1	1,679.10	1,679.10
1	129.10	129.10
1	4,274.05	4,274.05
2	381.90	763.80
4	5.10	20.40

Total Parts : 8,869.40

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 55114
Date Estimated : 14/05/2020
Prepared By : Chua Kee Sin

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFR8370M	WBATR92030LE25585	27/07/2018	X3 xDrive30i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/06/2018 @ 1110 Excess S\$ _____

Surveyor's Name Rahul Sign _____

Surveyor's Tel 900 600 68 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

No. of Working Days Recommend _____

Surveyor's E-mail _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Authorised Date _____

Surveyor's Tel _____

Surveyor's Name _____

Date & Time _____

Regn No. _____

Claim No. _____

Excess S\$ _____

Sign _____

Authorised Yes / No _____

Time _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,387.00
Parts	:	8,869.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	997.95
Grand Total	:	15,254.35

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **