

Form

CS3/ASM 20005814/R1P3

781K
LOG XPRY: 2022 / FEB

ASSIGNMENT

From _____ Date _____

Estimated Cost _____

OD / IP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **YN 28714**

at Workshop m/s **V fix**

of **26, CHIA PINH RD**
Insured: **AXA (ASM)**

Policy No _____

Claims No _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **32K**

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Est. Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **YN 28714**

2012 FEB

Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: **MITSUBISHI FE83BG05R06A 2977**

Colour: **WHITE** Insured / Std / NI / NA

Sp. Reading: **306472** Tfr. Insured / Std / NI / NA

Eng/No: _____

C/No: **FE83BEA20646**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: CR / S/Rim / STD A/Rim or

Tyre Size: F: **7-00-16LT**

R: **185 R14C**

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / HTSU / PIR / BUMI /

TOYO / YOKO or

Front

R/Bal. **6** mm R Bal. **5/5** mm

L/Bal. **6** mm L Bal. **5/5** mm

D.O.A. **10/03/2020** D.O.L. **19/05/2020**

Survey held at **U FIX**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Range of Repair & Days - (4k-5k) / 5 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

S + P + J

Photos

Sign

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Witness (\$

Ref: **Form 1**

Form 1, Form 2, Form 3

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	781K
Vehicle No.: YN2871U	
Vehicle to be Exported:	No
Intended Deregistration Date:	20 May 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	FE83BEOSRDEA
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	4M42A87943
Chassis No.:	FE83BEA20646
Maximum Power Output:	-
Open Market Value:	\$32,818.00
Original Registration Date:	21 Feb 2012
First Registration Date:	21 Feb 2012
Transfer Count:	2
Actual ARF Paid:	\$1,641.00

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	20 Feb 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$10,189.00
COE Rebate Amount:	\$7,033.00
Total Rebate Amount:	\$7,033.00

The information contained herein is correct as at 20 May 2020

OK



Used Mitsubishi Fuso Car for Sale



Merimen e-Claims



art.com/used_cars/info.php?ID=898249&DL=1000

► Mitsubishi Fuso Canter FE83

Overview

Financial

Accessories

Similar

Research

Photos

Ma

Price

\$32,000

Fuel Type

Diesel

Depreciation ⓘ

\$18,390 /yr

View models with similar depre

Reg Date

15-Feb-2012

(1yr 8mths 25days COE left)

Mileage

N.A.

Manufactured ⓘ

2011

Road Tax ⓘ

N.A.

Transmission

Manual

Dereg Value ⓘ

\$6,960 as of today (change)

OMV ⓘ

\$33,552

COE ⓘ

\$40,009

ARF

\$1,678

Engine Cap

2,977 cc

No. of Owners ⓘ

1

Curb Weight ⓘ

2,460 kg

Type of Vehicle

Truck

Description

14FT Freezer Box With Mitsubishi System. Vehicle In Good Condition. Class 3 Non VPCI Servicing Of Lorry And Freezer. With New Paint And New Cushion Seat. Fast Approval And Delivery. Call Now For Appointment.

Category

Direct Owner Sale

St

Al