

Form

CS3/ASM 20005814/R1P3

781K  
LOG XPRY: 2022 / FEB

ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: YN 28714  
at Workshop m/s: Vfix  
of 26, CHIA PINH RD  
Insured: AXA (ASM)  
Policy No \_\_\_\_\_  
Claims No \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 32K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: YN 28714 Date: 2012 FEB  
Type: M/Car / M/Cycle / Bus / Van / Truck / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: MITSUBISHI FE83BE05R06A 2977  
Colour: WHITE Insured / Std / NI / NA  
Sp. Reading: 306472 Tfr. Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: FE83BEA20646  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: CD / S/Rim / STD A/Rim or  
Tyre Size: F: 7-00-16LT  
R: 185 R14C  
ES / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / BUMI /  
TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_  
R/Bal. 6 mm R Bal. 5/5 mm  
L/Bal. 6 mm L Bal. 5/5 mm  
D.O.A. 10/03/2020 D.O.L. 19/05/2020  
Survey held at VFIX 4.35pm  
Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Review of Repair & Days - (4k-5k) / 5 days

SUBMIT PRS REPORT

DISMANTLE: 22/05/2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee

Transportation

S-P-R

Photos

Draw

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel Bal (\$

Ref: \_\_\_\_\_

Form: \_\_\_\_\_