

ASS. REC. BY:

REF: CT2 / 20005829 / K5

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SME 4595T Yr Regn: 09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Scenic c.c. 1461

Colour

M. Black A/C: Insured / Std / NI / NA

Sp. Reading

220999 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VFIRFA 00461280826

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 195/55R20

R:

BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

17/5/20

D.O.I.

21/5/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SME4595T
Make & Model : Renault, Grand Scenic IV 1.5 dCi AT
EU6,VF1RFA00461280826
Year of Manufacture : 2018

Estimation No. : E20050003
Date : 18/05/2020

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Amt S\$ 11,059.08

Discount (10.00%) S\$ 999.99

Subtotal S\$ 9,953.17

Section: Special nett

22	REAR PARKING SENSOR	mit 2.00	255.36	510.72	✓
23	REVERSE CAMERA	mit 1.00	707.88	707.88	✓
24	REVERSE CAMERA TRIM	1.00	157.80	157.80	7
25	WINDSCREEN SEALANT	me 2.00	25.00	50.00	4050
26	TAILGATE CLIPS	me 6.00	5.00	30.00	✓

Amt S\$ 1,456.40

Discount (0.00%) S\$ 0.00

Subtotal S\$ 1,456.40

Section: Labour

27	LABOUR FOR SPRAY PAINT TAILGATE, REAR BUMPER, REAR SPOILER, REAR END PANEL & REAR FENDER LH	1.00	1,600.00	1,600.00	6000
28	LABOUR FOR WELDING & KNOCKING REAR END PANEL AND ALL AFFECTED AREAS	1.00	1,000.00	1,000.00	7500
29	TO CHECK WIRING & SYSTEM FUNCTION	1.00	120.00	120.00	200
30	LABOUR FOR INSTALL NEW REAR WINDSCREEN GLASS	1.00	200.00	200.00	1200
31	LABOUR FOR INSTALL REVERSE SENSOR AND REAR IN CAR CAMERA	1.00	120.00	120.00	900
32	TO APPLY RUST PROOFING ON AFFECTED AREAS	1.00	100.00	100.00	7
33	TO CHECK TAILGATE WATER SEEPAGE	1.00	80.00	80.00	200
34	LABOUR FOR REMOVE & INSTALL ALL PARTS AS ABOVE	1.00	300.00	300.00	600
35	TO INSTALL REAR WINDSCREEN SOLAR FILM	1.00	200.00	200.00	1000

Amt S\$ 3,720.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 3,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remark Subtotal S\$ 0.00

Parts Subtotal S\$ 9,953.17

Special nett Subtotal S\$ 1,456.40

Labour Subtotal S\$ 3,720.00

Total S\$ 15,129.57

PAGE 2 OF 2

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SME4595T
Make & Model : Renault, Grand Scenic IV 1.5 dCi AT
EU6,VF1RFA00461280826
Year of Manufacture : 2018

Estimation No. : E20050003
Date : 18/05/2020

No.	Description	Qty	U/P	Amt
Section: Remark				
1	TP CLAIM AGAINST CHINA TAIPING INSURANCE SINGAPORE PTE LTD CLAIM NO: SNM20D201943 DOA: 17.05.2020 OIC: ADELINE CHNG SURVEYOR: KENNETH KONG (LKK)	1.00	0.00	0.00
				<i>Not Authorised</i>
				<i>Returning By Paint</i>
				<i>4-5 days</i>
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Parts				
2	REAR BUMPER	<i>CM</i> 1.00	1,152.96	1,152.96 ✓
3	REAR BUMPER LOWER MOULDING	<i>Re</i> 1.00	696.24	696.24 ✓
4	REAR BUMPER CENTRE BRACKET	<i>Ry</i> 1.00	357.84	357.84 ✓
5	REAR BUMPER SUPPORT BRACKET LH	1.00	113.88	113.88 ?
6	REAR BUMPER BRACKET LH	1.00	288.96	288.96 ?
7	REAR BUMPER REINFORCEMENT	1.00	685.68	685.68 ?
8	REAR WIPER ARM	<i>Sm</i> 1.00	160.92	160.92 X
9	REAR WIPER BLADE	<i>Sm</i> 1.00	39.00	39.00 X
10	TAILGATE LAMP LH	<i>CM</i> 1.00	548.88	548.88 ✓
11	TAILLAMP LH	<i>CM</i> 1.00	548.88	548.88 ✓
12	REAR LOGO 'DIAMOND'	<i>Re</i> 1.00	165.72	165.72 ✓
13	REAR EMBLEM 'RENAULT'	<i>Re</i> 1.00	130.56	130.56 ✓
14	REAR EMBLEM 'SCENIC'	<i>Re</i> 1.00	151.44	151.44 ✓
15	TAILGATE OUTER PANEL	1.00	755.40	755.40 ?
16	TAILGATE OUTER PANEL CHROME	1.00	473.16	473.16 ?
17	TAILGATE TOP SPOILER	<i>Re</i> 1.00	383.88	383.88 ✓
18	REAR WINDSCREEN GLASS	<i>Shatter</i> 1.00	954.24	954.24 ✓
19	TAILGATE ASSY	1.00	2,433.84	2,433.84 ?
20	TAILGATE HINGE LH	<i>R</i> 1.00	508.80	508.80 X
21	TAILGATE HINGE RH	<i>R</i> 1.00	508.80	508.80 X

Continue on next page...

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/05/2020 11:46
Date Of Accident	17/05/2020 17:40
Exact Location Of Accident	JURONG WEST AVE 4 SLIP RD TWDS JURONG WEST ST 64
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME4595T
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE. LTD.
Co Reg No	2XXXXX055D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96826300
Vehicle Particulars	
Manufacturer	RENAULT
Model	GRAND SCENIC IV-1.5 DCI EU6 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	M0014978
Cover Note Number	
Driver	
Name of Driver	LUI WEI MING
NRIC No	SXXXX354F
Date Of Birth	20/03/1973
Occupation	OUTDOOR
Date Of Driving Pass	13/07/1995
Driving Experience	24 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98164571
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 673C JURONG WEST STREET 65
#12-36
Postcode 643673
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20200517/2033

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD9949J
Vehicle Make/Model/Colour NISSAN DYNA
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver NG GUAN HOCK
NRIC/Passport Number SXXXX717G
Contact Number 96280372
Address 148 BUKIT BATOK WEST AVE 6
#12-371
Postcode 650148

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LUI WEI MING

Approximate Age

Injuries Sustain

5 DAYS MEDICAL LEAVE

Injured person in which vehicle?

SME4595T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address


673C JURONG WEST STREET 65
#12-36

Postcode

643673

SKETCH PLAN

JURONG WEST STREET 64



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report No: T/20200517/2033

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





SINGAPORE POLICE FORCE



T/20200517/2033

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20200517/2033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/05/2020 20:48	Vide Report No.:	Station Diary No.: 80
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LUI WEI MING			Address: APT BLK 673C JURONG WEST STREET 65 #12-36 SINGAPORE 643673		
ID Type / ID No.: NRIC NO / S7309354F			Contact No.: Home/Office: Mobile: 98164571		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 20/03/1973	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRIVATE HIRE DRIVER			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/05/2020 17:40	Type of Location: Bend
Location: Along Road 1 JURONG WEST AVENUE 4 JURONG WEST STREET 64 At the left turn filter lane.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD9949J	Lorry				Slightly Damaged	0
SME4595T	Car				Slightly	0

CONTINUATION OF REPORT

Driver				
Name	LUI WEI MING		ID No.	S7309354F
Related Vehicle	NIL		Contact No.	98164571
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 17/05/2020 at about 1735hrs, I was traveling along Jurong West Ave 4 and making a left turn toward Jurong West Street 64. I am driving a car with plate registration number SME4595T. I then make a left turn at the filter lane and made a complete stop to make way for oncoming vehicle coming from Jurong West Street 64. When I did a complete stop of my car, a lorry with the plate number GBD9949J hit the rear of my car. The rear of my car was smashed and the rear screen shattered. Both the lorry driver and myself exchanged particulars. My car was towed away and I immediately went to Mount Alvernia Hospital on my own. My car is installed with front car camera. I was given five(05) days Medical Leave and was informed by the car workshop to lodge a report.