



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number 69942623
Accident Reporting Number 69962672


Date Generated : 20/05/2020

User ID : BoonChewTay

### Section A - Accident Details

Registration Number	SMB1448X
Case Reference Number	BUS/05/20/1008
Registration Date	7/8/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Cheng Peipei
Type of Accident	Head to Rear
Accident Date and Time	14/5/2020 5:55 PM
Accident Reported Date and Time	14/5/2020 7:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1448X-REAR RIGHT PORTION SLB6557T (TP) INSURED WITH <b>AIG</b>
Prepared Date and Time	18/5/2020 9:55 AM
Chassis Number	WMAA22ZZ2E7002166
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, If applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$3,263.18	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$3,263.18</b>	<b>\$0.00</b>
Lump Sum Total	\$5,300.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	18/05/2020 10:08 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
00 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 08662672

Date Generated : 20/05/2020

User ID : BoonChewTay

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	1,060
Total Labour	\$1,325.00	

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	616.
Total Spray Painting & Panel Beating	\$708.00	

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298	VE	88-25225-6039	LAMP STOP-LED (MAN BUS)	1.00	\$1,141.70	10.00	\$2,055.08	Replace	✓ CK4
6010299	VE	88-25320-6008	LAMP INDICATOR-LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	X Svc
6010062	Body	F01001-CW273	COVER REAR TAIL LAMP RH FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	✓ CK4
6010464	VM	S01001-CW002	BRACKET ATTACHMENT FOR MAN A22 BUS	1.00	\$569.30	100.00	\$0.00	Repair	X R.
Total					\$3,959.80		\$4,078.98		

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 3 days

4/5.

After paint photo.

Sun Pm (Lkk)

20/03/2020

TP without prejudice.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: