



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 29/05/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1448X
Case Reference Number	BUS/05/20/1008
Registration Date	7/8/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Cheng Peipei
Type of Accident	Head to Rear
Accident Date and Time	14/5/2020 5:55 PM
Accident Reported Date and Time	14/5/2020 7:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106935
Special Instruction to ARC, if any	SMB1448X-REAR RIGHT PORTION SLB6557T (TP) INSURED WITH
Prepared Date and Time	18/5/2020 9:56 AM
Chassis Number	WMAA22ZZ2E7002166
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$708.00	\$616.00
Total Spare Part Cost	\$3,263.18	\$2,345.83
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,296.18	\$4,021.83
Lump Sum Total	\$5,300.00	\$4,000.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	18/05/2020 10:06 AM	20/05/2020 2:44 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/05/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$1,060.00
Total Labour	\$1,325.00	\$1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	\$616.00
Total Spray Painting & Panel Beating	\$708.00	\$616.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense


Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298	VE	88-25225-6039	LAMP, STOP: LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	Replace
6010299	VE	88-25320-6008	LAMP, INDICATOR: LED (MAN BUS)	0.00	\$1,274.10	0.00	\$0.00	Replace	Not Given
6010062	Body	F01001-CW273	COVER: REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010464	VM	S01001-CW002	BRACKET, ATTACHMENT: FOR MAN A22 BUS	1.00	\$569.30	100.00	\$0.00	Repair	Repair
Total					\$3,959.80		\$2,932.29		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



1,060
616
1,676

2,932.29
- 20%
2,345.832
1,676
4,021.83

415
\$4,000
3 days