REC. BY: Steve | REF. CC4/ASM20005875/EKa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
XX	

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMK 5796S Yr Regn: 16/4/99

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toyota Prius Plus c.c 1797

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: 91339 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDZS3EU 70J035790

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal	5 mm	R/Bal.	5 mm
L/Bal	5 mm	L/Bal	5 mm
D.O.A	19/5/20	D.O.I.	21/5/20

Survey held at: My Car Consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear L4

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 93K

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp ($ _____) ☐ Interview ($ _____) ☐ Tech Inve ($ _____) ☐ Weed and ($ _____)

Report Format: _____

Lump Sum / I.B.I: ($ _____)

Survey Fee: _____

Transportation: _____ $ - RS. _____ $

Photos: _____

Other: _____

TOTAL: _____