





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/05/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1430X
Case Reference Number	BUS/05/20/1012
Registration Date	10/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Jasni Bin Harun
Type of Accident	Side Swipe
Accident Date and Time	18/5/2020 4:00 PM
Accident Reported Date and Time	18/5/2020 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106970
Special Instruction to ARC,if any	SMB1430X-RIGHT FRONT PORTION GBG4532U (TP) INSURED WITH NTUC
Prepared Date and Time	22/5/2020 8:21 AM
Chassis Number	WMAA22ZZ5E7002145
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$708.00	\$616.00
Total Spare Part Cost	\$189.60	\$189.60
Total Other Cost	\$0.00	(\$229.20)
TOTAL COST	\$1,692.60	\$1,106.40
Lump Sum Total	\$1,700.00	\$1,100.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	22/05/2020 8:26 AM	22/05/2020 8:42 AM
Signature		
Remarks	\$3,705.20	

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/05/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00				\$530.00		
Total Labour			\$795.00				\$530.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$708.00				\$616.00		
Total Spray Painting & Panel Beating			\$708.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$229.20)		
Total Other Costs			\$0.00				(\$229.20)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010164	GLASS	4001X01-GLASS5173	GLASS,SIDE:R1,FOR MAN A22 BUS	1.00	\$994.80	100.00	\$0.00	Repair	Repair X R
6010165	GLASS	4001X01-GLASS5174	GLASS,SIDE:R2,FOR MAN A22 BUS	1.00	\$970.40	100.00	\$0.00	Repair	Repair X R
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	1.00	\$37.00	0.00	\$37.00	Replace	Replace / Npc
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	Replace / Npc
Total					\$2,202.20		\$237.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,146

P=237  
L=1,146  
-----  
1,383  
- 209  
-----  
1,106.4

45  
\$1,100      2 days