

## COMFORTDELGRO PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHD6505E

21/05/20

MAKE :

### CHIANG/AIG

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER <del>x(R)</del>		\$459.40
1	REAR BUMPER CENTRE MOULDING <del>ref</del>		\$451.25
1	REAR BUMPER SIDE BRACKET RH /LH <del>xun</del>		\$33.10
10	REAR BUMPER COVER CLIPS <del>xun</del>		\$2.20
	<b>SUB TOTAL</b>		<b>\$998.85</b>
	<b>20.00%</b>		<b>\$199.77</b>
	<b>DISCOUNTED TOTAL</b>		<b>\$799.08</b>
1	REAR REVERSE SENSOR <del>xun</del>		\$135.70
			<b>\$135.70</b>
	<b>Labour Charge</b>		
	Panel Beating	\$240	\$500.00
	Spray Painting Charge	\$200	\$280.00
	Check wiring	\$30	\$60.00
	Tuff Kote	<del>xun</del>	\$60.00
	Remove/refix Reverse sensor		\$60.00
	<b>TOTAL LABOUR</b>		<b>\$960.00</b>
	<b>ESTIMATE TOTAL</b>		<b>\$1,894.78</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rm (LKK) 1#345

22/05/2020

Raresurvey@lkkauto.com

88622778

add repair photo

P/S

2+ pp 9.1 day 5

### Workshops

59 Loyang Drive Singapore 508969  
383 Sin Ming Drive Singapore 575717  
45 Pandan Road Singapore 609286  
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156  
7 Sungei Kadut Way Singapore 728791  
501 Yishun Industrial Park A Singapore 768731

A member of COMFORTDELGRO

Date/Time: 22.05.2020 11:47

Page : 1

Team: ARC Repair TP(CLSO)1

### JOB CARD

Sales Order:

JC NO.: 305400095

STOMER

/MS COMFORT TRANSPORTATION PTE LTD  
STOMER NO. 7010045  
DRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
.. (R) 65508755 (O)  
(P)

REGN NO.:

SHD6505E

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN  
22.05.2020 09:00

YR OF MANU.

23.01.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU188934


COMPLETION DATE/TIME:

COUNT CARD NO.

### JOB DESCRIPTION

Accident Date: 21.05.2020  
NATURE: 3P 21.05.2020

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SHD6505E CHIANG

Vehicle No.: SHD6505E

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard