



1 of 3

Report No. T/20180109/2164

Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE

Tel No: 1800-4849999

Date/Time Report Made: 09/01/2018 20:31			Vide Report No.:	Station Diary No.: 126		
Informa	nt's Partic	ulars				
Name of Informant: ZULKARNAIN BIN AZMAN			Address: APT BLK 328 TAH CHING ROAD #01-08 SINGAPORE 610328			
ID Type / ID No.: NRIC NO / S9336164D			Contact No.: Home/Office:	Mobile: 86594124		
National SINGAP	ity: ORE CITIZ	EN	Email:			
Sex: Male	Age:	Date of Birth: 07/10/1993	Type of Informant: Driver			
Race: Malay			Language:	Institution / School Name:		
Occupation: CNB officer		E	Driving Licence Information: Class: 2B,3	Date of Expiry:		

Type of Accident:	Non-Injury Government Vehicle		Drink Drive: No	Date/Time of Accident: 09/01/2018 17:30		Type of Location: Slip road	
BUKIT TIMAH KRANJI EXPF Along BKE tov Lamp Post Nu	wards KJE exit near la	amp post 2	ATTACHEN TO STORE AND THE		Pop	d Speed Limit	
Weather: Raining		Wet	Road Surface: Wet			Road Speed Limit:	
Traffic Flow:			c Control: Controlled			Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear					one conveyed by oulance:		

Details of V	1 (0-2 (0-2 (0-2 (0-2 (0-2 (0-2 (0-2 (0-2	Commence of the Commence of th			Call Call Control Control	
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
SJF3948X	Car				Seriously	0
					Damaged	
SLD103Z	Car				Slightly	0
			E		Damaged	
SLL9162B	Car				Seriously	1
	0.000				Damaged	





Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No: 1800-4849999 2 of 3 Report No. T/20180109/2164

CONTINUATION OF REPORT

Brief Details.

On the 09/01/2018 at about 1730hrs, I was driving a CNB unmarked vehicle which originally bore the registration plate number of QX1320S and the car plate now is SLL9162B along BKE towards KJE exit near to lamp post 282S1.

The car In front of me bearing registration plate number of SLD103Z suddenly applied it's brakes so I also applied my brakes. The car behind of me bearing registration plate number of SJF3948X could not brake in time and it's front bumper collided into my car's rear bumper.

The rear vehicle's owner and me went out of our vehicles to make a check on the damages while the front vehicle drove further in front and stopped at the road shoulder. No one was injured during the accident. My car's rear bumper was severely dented in while the rear car's front bumper was severely dented in. The front car's driver came and told us that my car's front bumper had collided into her car's rear bumper.

I went to make a check and discovered that my car's front car plate number was slightly dented in but I could not notice any damages on the front car's rear bumper at that point of time. I only realized what looks like slight scratches on the front car's rear bumper now when I am doing this report after looking at the photos I took of the scene. We all exchanged particulars and I informed them that the car we were driving was a government vehicle and that they were required to lodge a traffic accident report and they acknowledged.





Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No: 1800-4849999 3 of 3 Report No. T/20180109/2164

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt 1 YEO JUN BIN	Signature Of Informant:	
Signature Of Interpreter: Not applicable	Date/Time: 09/01/2018 20:31	
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:	