

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/05/2020 13:06
Date Of Accident 19/05/2020 16:50
Exact Location Of Accident AYE/CITY EXIT 9
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBD3151H
Insured/Policyholder
Name Of Registered Owner DB ACOUSTICS PTE LTD
Co Reg No 1XXXXX490C
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-67351006

Vehicle Particulars

Manufacturer NISSAN
Model CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company ERGO INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number DMCG19007679
Cover Note Number

Driver

Name of Driver TAN CHENG YEOW
NRIC No SXXXXX633H
Date Of Birth 23/05/1967
Occupation OUTDOOR
Date Of Driving Pass 28/06/1996
Driving Experience 23 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97378696
Fax Number
Contact Number
Email Address ADMIN@CLAUTO.COM.SG

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 19th May 2020, around 4.48pm, I'm driving my company Lorry GBD3151H on left inner lane from AYE toward city, exit "Exit 9". I travel on the center lane and this lane only for right turn. I stop at Junction and traffic light was red. I was stop behind Nissan Van GBE568D. This van is 1st Vehicle stop at the Junction and was driving by Mr. Noor Azman Mohamed Ameen (NRIC Sxxxx041C). My Lorry GBD3151H is 2nd (center) Vehicle and stop at safety distance of a vehicle space for about 5-10 second. From my Lorry GBD3151H center inner roof back view mirror, I notice a big Prime Mover XD770E driving by Mr Chan Weng Loong (NRIC Sxxxx047H) with speed came toward my lorry without slow down. To prevent serious accident, I driver my Lorry GBD3151H move forward and stop with safety distance behind the Van GBE568D. However, the Prime Mover XD770E couldn't stop and collapsed against my Lorry GBD3151H rear center portion. Due to Prime Mover Xd770E strong impact, push my Lorry GBD3151H move forward, hit against the fron Van GBE568D and cause my Lorry GBD3151H front damaged. Photos prove my Lorry GBD3151H front have minor damaged by Lorry rear center was badly damaged. Photos also prove the Prime Mover XD770E front was badly damaged. This accident I will not liable at all.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE568D
Vehicle Make/Model/Colour	NISSAN / NV350 PANEL VAN 2.5 5AT 5DR EURO V
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NOOR AZMAN MOHAMED AMEEN
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

XD770E

Vehicle Make/Model/Colour

MITSUBISHI / FP517DR2RDEB

Details Of Properties

CHAN WENG LOONG

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 11/05/20


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 21/5/20

Verified By ASAX MARS
 Reporting officer 

Reporting Centre Personnel's Signature
 Name: Aislinn Bin Atan
 NRIC/FIN No: S746826C

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19th May 2020, around 4.48pm, I'm driving my company Lorry GBD3151H on left inner lane from AYE toward city, exit "Exit 9". I travel on the center lane and this lane only for right turn. I stop at Junction and traffic light was red. I was stop behind Nissan Van GBE568D. This van is 1st Vehicle stop at the Junction and was driving by Mr Noor Azman Mohamed Ameen (NRIC Sxxxx041C). My Lorry GBD3151H is 2nd (center) Vehicle and stop at safety distance of a vehicle space for about 5-10 second. From my Lorry GBD3151H center inner roof back view mirror, I notice a big Prime Mover XD770E driving by Mr Chan Weng Loong (NRIC Sxxxx047H) with speed came toward my lorry without slow down. To prevent serious accident, I drive my Lorry GBD3151H move forward and stop with safety distance behind the Van GBE568D. However, the Prime Mover XD770E couldn't stop and collapsed against my Lorry GBD3151H rear center portion. Due to Prime Mover XD770E strong impact, push my Lorry GBD3151H move forward, hit against the front Van GBE568D and cause my Lorry GBD3151H front damaged. Photos prove my Lorry GBD3151H front have minor damaged but my Lorry rear center was badly damaged. Photos also prove the Prime Mover XD770E front was badly damaged.

This accident I will not liable at all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 21/05/20



[Signature]

Driver's Signature

(If Driver is not the policyholder)

Date & Time: 21/5/20

Verified By ADAX MAR
Reporting officer *[Signature]*

Reporting Centre Personnel's Signature

Name: AIZAM BIN ATAN

NRIC/FIN No: S7464826C