

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIED WORLD A	SSURANCE COMPANY LTD	Ref:	CS/AWA20005920/Atf3e2	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON	Date:	24/09/2021	
			Code	: AWA	
1.	, , , , , , , , , , , , , , , , , , ,				
	Insured Veh.	XD 770E	Veh. Inspected	GBD 3151H	
	Policy No.	BVFCSB0013452001	Coverage (\$)	0.00	
	Claim No.	NSV20000174/PC	Excess (\$)	0.00	
	Assign From	WONG KIN	Assign Date	26/05/2020	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN CABSTAR	c.c	2953	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	JN1SC2F24Z0856253	Colour	SILVER	
	Odometer	254050 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
	L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
	R/H Rear Tyre	155 R13	YOKOHAMA	6 mm	
	L/H Rear Tyre	155 R13	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/05/2020	Inspection Date	26/05/2020	
	Survey held at	VISION AUTOWORK PTE LTD			
	8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

13 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: