



PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20005933/Evf3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 29-05-2020		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XD 7467K	Veh. Inspected	SKN 3548M	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023360	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	26/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA200	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD1173432N092302	Colour	GREY	
Odometer	123782 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information				
Accident Date	23/05/2020	Inspect Date / Time	26/05/2020 (03:00 PM)	
Survey held at	AKA AUTO-25 KAKI BUKIT RD 4 #05-37 SYNERGY @KB			
Repairer	-			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20005933/Evf3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.