

ASS. REC. BY: H. ANN

REF:  CS3/III20002551/Fvf3-1

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 14.2.2020

Veh No: SKC 6509P Yr Regn: 13/54/2010  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or \_\_\_\_\_

To Inspect Vehicle No: SKC 6509P

Make: Subaru Impreza c.c. 1498

at Workshop m/s GV Motormworks  
of 6B Kaji Bukit Ave 6 #01-10

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 185048 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: JF1GH3K5594035389

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

(Client's Record) \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Make of Veh: winsa -> 68449012

Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 225/45/R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_

Front R/Bal. 5 mm Rear R/Bal. 5 mm

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 5 mm L/Bal. 5 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

D.O.A. 24/1/20 D.O.I. 14/2/20

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Survey held at GV motormworks 3-23pm

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

CA / REV / REP. / 24 HRS mp Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time	Action / Instruction
	<u>Range - 115 - 2.5k</u>
	<u>mp days - 3 day</u>
	<u>* SKC 6509P</u>
	<u>PRS case A</u>
	<b>RECEIVED 24 FEB 2020</b>
	<u>INV - 12000</u>
	<u>PV - 7404</u>
	<u>NV - 4500</u>
	<u>17/2/2020</u>

Date / Time	Action / Instruction
	<u>Range - 115 - 2.5k</u>
	<u>mp days - 3 day</u>
	<u>* SKC 6509P</u>
	<u>PRS case A</u>

Date/Time, File Pass to?  Prel. Report  Final Report

Days Of Repair: 4  
Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to? \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_

1) 24/2 typist  
28/5/20-Typist

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)

Report Format: PRS-PS

Photos \_\_\_\_\_  
Others \_\_\_\_\_

Lump Sum / L.B.I: (\$ LS \$2500)

TOTAL \_\_\_\_\_