



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20000940/Gsf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 01-06-2020



ATTN : BERNARD LER

Code : AIG

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |              |                       |            |
|---------------------|--------------|-----------------------|------------|
| <b>Insured Veh.</b> | SGF 766J     | <b>Veh. Inspected</b> | SKC 7425R  |
| <b>Policy No.</b>   | 1800039202   | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | 9617567881SG | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | BERNARD LER  | <b>Assign Date</b>    | 27/05/2020 |

#### 2. Vehicle Particulars & Condition

|                         |                   |                     |                    |
|-------------------------|-------------------|---------------------|--------------------|
| <b>Make &amp; Model</b> | AUDI A6 2.8       | <b>c.c</b>          | 2773               |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2011               |
| <b>Chassis No.</b>      | WAUZZZ4G8BN023912 | <b>Colour</b>       | BLACK              |
| <b>Odometer</b>         | 162818            | <b>Steering</b>     | IN ORDER           |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | STANDARD ALLOY RIM |
| <b>General</b>          | GOOD              |                     |                    |

#### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 245/40Z R18 | FALKEN      | 6 mm           |
| <b>L/H Front Tyre</b> | 245/40Z R18 | FALKEN      | 6 mm           |
| <b>R/H Rear Tyre</b>  | 245/40Z R18 | FALKEN      | 6 mm           |
| <b>L/H Rear Tyre</b>  | 245/40Z R18 | FALKEN      | 6 mm           |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

|                       |                                                                     |                        |            |
|-----------------------|---------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 10/01/2020                                                          | <b>Inspection Date</b> | 16/01/2020 |
| <b>Survey held at</b> | LENG WANG MOTOR<br>BLK 3007 UBI ROAD<br>#01-414<br>SINGAPORE 408701 |                        |            |

#### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

|                                            |                       |
|--------------------------------------------|-----------------------|
| <b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b> | <b>2 Working Days</b> |
|--------------------------------------------|-----------------------|