

ASS. REC. BY:

Rasul

REF:

CC4/FCI 20005981

Kaz

9033

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMA 2335L

at Workshop n/s PERFORMANCE

of 303, ALAMARA RD

Insured: FCI

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 134K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 2335L

Yr Regn: 2018/MAY

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X1 S0RWE18E c.c. 1499

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

18499

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAJG D080EG22187

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

25/05/2020

D.O.I.

07/07/2020

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.R. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

> Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	903J
Vehicle No.:	SMA2335L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jul 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I LED NAV MSPT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	F909H714B38B15A
Chassis No.:	WBAJG12080EG22187
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$38,207.00
Original Registration Date:	31 May 2018
First Registration Date:	31 May 2018
Transfer Count:	0
Actual ARF Paid:	\$42,690.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2028
PARF Rebate Amount:	\$32,017.00

COE Expiry Date:	30 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,989.00
COE Rebate Amount:	\$29,992.00
Total Rebate Amount:	\$62,009.00

The information contained herein is correct as at 07 Jul 2020

OK



Used 2018 BMW X1 sDrive18i for



Merimen e-Claims



PARF/COE R

rt.com/used_cars/info.php?ID=906697&DL=2370

▶ BMW X1 sDrive18i

Overview

Financial


Accessories

Similar

Research

Photos

Map

 CAR HOUSE PTE LTD

Price \$134,800

Depreciation  \$14,710 /yr
View models with similar depreReg Date 18-May-2018
(7yrs 10mths 10days COE left)

Mileage 33,188 km (15.5k /yr)

Manufactured  2017Road Tax  \$684 /yr

Transmission Auto

Dereg Value  \$58,939 as of today (change)OMV  \$33,005COE  \$38,501ARF  \$38,207

Engine Cap 1,499 cc

Power 103.0 kW (138 bhp)

Curb Weight  1,430 kg

No. of Owners 1

Type of Vehicle SUV

Features

BMW TwinPower Turbo 3 Cylinder Engine With 138Bhp, 220Nm Of Torque. 0-100Km/H In 9.7s, Top Speed 200Km/H, 7 Speed Transmission DCT, Front Wheel Drive. View specs of the BMW X1