

ASSIGNMENT

From

Date

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLX8062A
hockwog

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$33k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1526

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

30/10 mth plus.see untl 7-4-2014 LTA 26829rep 15k. nett 6171* TOTAL LOSS urgent. have video of folder - Not economical to repair.nett loss 6171MV: \$33000.00LTA Rebae: \$26829.00NV: \$6171.00

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

Veh No: SLX8062AYr Regn: 8/4/11Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or FAMake: Toyota Lexus RX400h c.c. 3456Colour: white

A/C: Insured / Std / NI / NA

Sp Reading: 132172

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTJBC11A102041476Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

235/602R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 26/5/20D.O.I. 28/5/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof orO/S body, n/s rear &The U/C / Chassis frame / body structure affected due to collision.