

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 28.05.2020

Time: 15:18:49

Page: 1

Big Asia
C4S

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305401231
 REGN NO : SHD4626C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 06.06.2013
 DATE/TIME IN : 28.05.2020 09:45
 ACCIDENT DATE : 28.05.2020

1530

LKK - Ram

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0101-0010-G	REAR SUSP.UPR ARM LH	1	321.70	20.00	257.36	?
0002 03-01-0101-0040-G	REAR SUSP.LWR ARM LH	1	195.80	20.00	156.64	?
0003 03-01-0101-0042-G	REAR WHEEL KUNCKLE ARM LH	1	550.80	20.00	440.64	?
0004 03-01-0199-0021-G	REAR SHOCK ABSORBER LH	1	190.60	20.00	152.48	?
0005 03-01-0199-0083-G	REAR WHEEL BEARING/HUB LH	1	384.60	20.00	307.68	?
0006 03-01-0199-0085-G	REAR WHEEL RIM LH	1	284.70	20.00	227.76	Scr
0007 03-01-0101-0002-G	REAR WHEEL CAP LH	1 L	145.00	20.00	116.00	Cra

SUB-TOTAL : 1,658.56

JOB NATURE

0000 PB	PANEL BEATING-Rear Fender LH	300.00	\$240
0001 SP	SPRAYPAINT-Rear Bumper ETC	500.00	\$400
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	\$30
0003 L	R/I REAR SUSPENSION LH	300.00	?

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 28.05.2020

Time: 15:18:49

Page: 2/2

Arg Asia
CLS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305401231
REGN NO : SHD4626C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 06.06.2013
DATE/TIME IN : 28.05.2020 09:45
ACCIDENT DATE : 28.05.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 L	WHEEL ALIGNMENT	120.00		\$80		
0005 23-01	TOWING FEE-King Dolly	150.00				
0006 20-05	REAR WHEEL TYRE LH	207.00		xm		
SUB-TOTAL :						1,617.00

TOTAL : 3,275.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram CLK
29/05/2020 11:15
Ram CLK@clxtracto.com
88622778

(45)

add repair photo

2 repairer

Requesting for
Book value

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Orchard Road Singapore 249645

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 28.05.2020 15:00

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.:305401231

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO. SHD4626C	MILEAGE
OWNER NO. 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL SONATA	DATE/TIME IN 28.05.2020 09:45
	YR OF MANU. 06.06.2013	TARGET DATE
	CHASSIS CODE KMHET41VMDA834628	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 28.05.2020

NATURE: 3P 28.05.2020

1/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Assignment Slip

Exit Pass

No.: SHD4626C LIMITS

Vehicle No.: SHD4626C

Signature/Date

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Pandan Road Singapore 609649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 28.05.2020 15:00

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.:305401231

CUSTOMER
COMFORT TRANSPORTATION PTE LTD
IS 7010045
CUSTOMER NO. 383 SIN MING DRIVE
ADDRESS Singapore SINGAPORE 575717
65508755

REGN NO. SHD4626C	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 28.05.2020 09:45
YR OF MANU. 06.06.2013	TARGET DATE
CHASSIS CODE KMHET41VMDA834628	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 28.05.2020

NATURE: 3P 28.05.2020

S/NO LABOR CODE DESCRIPTION



SIGNED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHD4626C LIMITS

Vehicle No.: SHD4626C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard