



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS3/AGI19012561/Gqf3e2-1

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 05-06-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 8231R	Veh. Inspected	SKZ 3206L
Policy No.		Coverage (\$)	0.00
Claim No.	C10003510/JM	Excess (\$)	0.00
Assign From	JULIE	Assign Date	29/05/2020

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI GRANDIS 2.4	c.c	2378
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JMYLRNA4W9Z000237	Colour	SILVER
Odometer	185918	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	WEST LAKE	6 mm
L/H Front Tyre	215/55 R17	WEST LAKE	6 mm
R/H Rear Tyre	215/55 R17	WEST LAKE	6 mm
L/H Rear Tyre	215/55 R17	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/06/2019	Inspection Date	17/07/2019
Survey held at	BLK 3014 UBI ROAD 1 #01-278 S'PORE 408702		
Repairer	VICTOR'S GARAGE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------