

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
UNITED OVERSEAS INSURANCE LTD Ref : CS/UOI20006059/Dvf3e2				Ovf3e2	
3 ANSON ROAD #28-01			Date: 22-06-2020		
SPRINGLEAF TOWER SINGAPORE 079909			Code: UOI2		
4		Delieu Destieulese			
1.	Insured Veh.	SLJ 9396D	:- THIRD PARTY CLAIM	SLC 6809L	
	Policy No.	3LJ 9390D	Veh. Inspected Coverage (\$)	0.00	
	Claim No.	SLJ 9396D	Excess (\$)	0.00	
	Assign From	JOSEPHINE WONG	Assign Date	01/06/2020	
0	Assign From		L	01/00/2020	
2.	Make & Model	MAZDA 5 WAGON	culars & Condition	1998	
		HIDDEN	c.c Year of Reg.	2016	
	Engine No. Chassis No.	JM6CW1071G0123348	Colour	BLACK	
	Odometer	55348		IN ORDER	
	Brakes	IN ORDER	Steering Modification	SPORTS RIM	
	General	GOOD	Modification	SPORTS KIW	
3.	Joenst Line Control of the Control o				
Size Make Balance					
	R/H Front Tyre	225/45 R17	GOODYEAR	5 mm	
	L/H Front Tyre	225/45 R17	GOODYEAR	5 mm	
	R/H Rear Tyre	225/45 R17	GOODYEAR	5 mm	
	L/H Rear Tyre	225/45 R17	GOODYEAR	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
0.	Accident Date	31/05/2020	Inspection Date	01/06/2020	
	Survey held at	RALLY PITSTOP	mopositori Buto		
	our roy mora at	176 SIN MING DRIVE			
		#04-17 SIN MING AUTO CARE SINGAPORE 575721			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•				