

12300000

ASS. REC. BY:

REF: 093/ 8M020003976/ Qvf3-1

Initial Instructions:

Surveyor:

ASSIGNMENT (Office)

From (Person) Gnoh, Pau Loong

of 3MD

Date/Time: Monday, June 1, 2020 4:58 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8MQ 2359J

Insured: SLZ 7979B

at Workshop m/s ECO Automobile

Tel: 9176 5733

of 13 Kaki Bukit Road 4 # 03-29 Bentley Biz

Policy No:

Claim No: CMTD2001116/GPL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/03/2020

CA / REV / REP. / REV 24HRS (up)

H.O.D. Endorsement:

Date/Time: 2:07pm 13/3/2020 Person Contacted: Alfie

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	8MQ 2359J-X	
	SLZ 7979B-X	
17/3/20	- survey taken	
16/3/20	- survey taken	
17/3/20	- party work up	
18/3/20	Submit PRS. Est repair range \$6000 - \$7000	

2/6/20 Submit LS \$6900 (Red 4400, 39%), 4 days