

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/06/2020 13:52
Date Of Accident	02/06/2020 20:40
Exact Location Of Accident	PIPIT RD OUTSIDE BLK 54 CARPARK ENTRANCE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC4112P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUPREME LEASING & LIMOUSINE PTE LTD
Co Reg No	2XXXXX190R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

### Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID 1.8S CVT
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19-MK000858-R00
Cover Note Number	

### Driver

Name of Driver	TAN CHUNG MING (CHEN ZONGMING)
NRIC No	SXXXX921D
Date Of Birth	30/06/1975
Occupation	OUTDOOR
Date Of Driving Pass	04/09/2000
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88221789
Fax Number	
Contact Number	OFFICE-88221789
E-Mail Address	NOEMAIL

Address	BLK 637 VEERASAMY ROAD #12-105
Postcode	200637
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JTC7141 (MOTORCYCLE)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 629 BEDOK RESERVOIR ROAD #01-1620 , <b>POSTCODE:</b> 470629 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4439999 - <b>FAX NO:</b> 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO POLICE REPORT - T/20200603/2042.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JTC7141
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)



Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/06/2020 at about 2040 hrs at along Pipit road outside Car Park entrance of BIK 54. I was travelling on the extreme Right lane along Pipit Road and when making a Right turn into the above mentioned Car Park entrance, suddenly a vehicle (B) overtaking my vehicle from the Right without proper lookout and without caution hence collided onto my Right Portion of my vehicle (A) causing damages to my vehicle. I have one passenger inside my vehicle.

(A) SMC 2112 UP  
(B) JTC 7141

Note: Please note that your insurer may have 14 days time frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check your policy for more information.

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Police Report



SINGAPORE  
POLICE FORCE



T/20200603/2042

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

2 of 3

Report No. T/20200603/2042

CONTINUATION OF REPORT

<b>Driver</b>			
Name	TAN CHUNG MING		ID No. S7518921D
Related Vehicle	NIL		Contact No. 88221789
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 02/06/2020 at about 2040hrs, I am a Grab driver and I have one male Malay passenger onboard. I was driving my black Toyota CHR, SMC4112P at the first lane along Pipit road and was turning right towards the carpark entrance of Blk 54 Pipit Road. Suddenly, one malaysia blue and black Yamaha motorcycle, JT07141 overtook my vehicle recklessly from the right without making a check hence it collided onto the right portion of my vehicle. During which, we managed to exchange particulars and I observed that there were minor injuries on his right arms and knees. So far, I have called the driver several times however he did not answer my phone call. My vehicle do not has any in-car camera and there is no witness. There is a CCTV at the carpark gantry entrance. I am not injured. Due to the collision, my vehicle's right passenger door has some scratch

Police Report



SINGAPORE  
POLICE FORCE



T/20200603/2042

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

3 of 3

Report No. T/20200603/2042

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Staff Sgt HEAP ZHI YONG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/06/2020 13:19
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172	Classification Of Case:
Authentication Stamp NP168	

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





TOYOTA MOTOR CORPORATION JAPAN

MODEL DAB-ZYX10-AHX1B1997 ml

ENGINE ZAX-EXE


FRAME No. ZYX10-2031938

COLOR 209 FC28 M31

TRIM PLANT OPTION

P610 -03A

872



Accident Photo

