Surreyor: Kan	SSIGNMENT
From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s of Insured: Policy No. Claims No. Sum Insured: Excess:	Veh No: SHO JOAAG Yr Regn: 11 03/20 Type: M.Car / M.Cycle / Bus / Van / Lorry Taxi / Prime Mover / Truck / Trailer or Make: Hymdai Long 3 c.c 158C Colour Bull A/C: Insured / Std / NI / N Sp.Reading 810 T/Radio: Insured / Std / NI / N Eng/No: C/No: KMHC85\Cvl U189802 Gen. Cond Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record) Make of Veh:	Brake: Inorder Jammed / Leaked / Burnt or Modi: Nil / SRim / STD A/Rim or Tyre Size: F: 195/65/815
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.	Tyre Size: F: 195 65 R15 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	Front Rear R/Bal. 9 mm R/Bal. 9 mm L/Bal. 9 mm D.O.A. 3/06/2020 D.O.I. 3/06/2020 Survey held at Constant delsa (Loyare)
CA / REV / REP. / 24 HRS Vehicle: IN / OUT Date: Person Contacted:	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	The Plan
	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:
2) Add Fee	

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

gapore 508969 bl: 6214 8300



TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

LKK-Ram.

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

03/06/2020

Policy No: Vehicle Reg. No.:

SHD4044G

Date of Loss: Driveable?

NO

Party At Fault:

UNKNOWN

Vehicle Reg.

11/03/2020

Make/Model:

HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Date:

GOOD

Vehicle Colour:

BLUE

Gen Condition:

KMHC851CVLU189802

Engine No:

G4LEKU408597

Chassis No:

Odometer: 0 KM

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NO

Est. Duration of Repair

(day)

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		1,802.20
Miscellaneous Items		11.00
Labour		1,260.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	3,073.20
	+ GST 7.00% (S\$)	215.12
	Nett Amount (S\$)	3,288.32

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 03 Jun 2020)

Parts:

192

HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Print Code: ComfortDelGro Engineering Pte Ltd/SHD4044G/03/06/2020 13:24

Estimates on Parts

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*FRT FENDER LH CIALON	20.00	0.00	*490.70 FL
2	1	*FRT FENDER (HYBRID) LH	20.00	0.00	*26.60 FL
3	1	*WING MIRROR LH DM/SCr	20.00	0.00	*1,391.70 FL
4	1	*FRT DOOR (COMFORTDELGRO) LHINEC	0.00	0.00	*75.00 F
5	1	*FRT FENDER ADVERTISEMENT STICKER LHVec	0.00	0.00	*100.00 F
6	1	*FRT DOOR ADVERTISEMENT STICKER LHWC	0.00	0.00	*100.00 F.
F=Fra	nchise part. L=ListIte	emDisc.			
		Sub Total (S\$)			2,184.00
		- List Item Discount on L Items (S\$)			381.80
		Total Parts (S\$)			1,802.20

ComfortDelGro Engineering Pte Ltd/SHD4044G/03/06/2020 13:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount	
Mis	cellan	eous Items			
1	1	OD/TP Case (Insurer)		11.00	
			Sub Total (S\$)	11.00	

Estimates on Labour

No	Particulars	Lab.Type	,	Amount
Lab	our Items			
1	PANEL BEATING	New	\$480	600.00
2	SPRAY PAINTING	New	\$400	600.00
3	TUFF KOTE	New	830	60.00
		Gross Labour Cost (S\$)	•	1,260.00

ComfortDelGro Engineering Pte Ltd/SHD4044G/03/06/2020 13:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pancier)
3/06/2020 (A10

Paresuran archanto.com

Pares

OMFORTDELGRO

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156 7 Sungel Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

Date/Time:320037:06:202086413:02

Page: 1

eam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: JC NO.:305402212

MILEAGE

FUEL

OMER

ESS

(R) (P)

COMFORT TRANSPORTATION PTE LTD

7010045

OMER N 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

IONIQ(G3)

03.06.2020 10:45

YR OF MANU 11.03.2020

REGN NO. SHD4044G

HYUNDAI

TARGET DATE

CHASSIS CODE KMHC851CVLU189802 COMPLETION DATE/TIME:

DUNT CARD NO.

JOB DESCRIPTION


ccident Date: 03.06.2020

ATURE: 3P 03.06.2020

/NO

LABOR CODE

DESCRIPTION



	e e		
KED & PASSED OUT BY:			2
SERVICE ADVISOR	,	CUSTOMER'S SIGNATURE	
dgement Slip	* Exit Pass		
SHD4044G LIMTS	Vehicle No.: SHD4044G		

turned to Service Reception upon collection

Service Advisor

Signature/Date Name of Service Advisor

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCI	MΕ	MT.	CTAI	T = N	ENT
ACC		ш	SIA	-17	

Date Of Report

03/06/2020 11:10

Date Of Accident

03/06/2020 08:00

Exact Location Of Accident

ANG MO KIO AVE 10 X AMK AVE 3

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD4044G

Insured/Policyholder

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

Co Reg No

1XXXXX821R

Email Address

FLEETSAFETY@CDGETAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer

HYUNDAI

Model

IONIQ

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

MCOM0015

Cover Note Number

Driver

Name of Driver

HUSSIN BIN IDRIS

NRIC No

SXXXX839J

Date Of Birth

02/05/1958

Occupation Date Of Driving Pass OUTDOOR

29/05/1984

Driving Experience

36 YEARS AND 0 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-96248328

Fax Number

Contact Number

EMail Address

KAWAII_SITI@YAHOO.COM.SG

BLK 109 ANG MO KIO AVENUE 4 Address

#12-26

560109 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - TAXI DRIVER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

Was any other material or property damaged?

ambulance?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name

PASIR RIS NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 1 PASIR RIS DRIVE 4, POSTCODE: 519457, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-5852999 - FAX NO: 65855261

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T20200603/2018 * TYPE OF ACCIDENT :- HIT & RUN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YN8297M

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

UNSURE

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

SKETCH PLAN	
	Ang Molar Are 10
	(18 P) SHD4044G B) YN8297M
	D) YN8297M
 	
	Amik Ave 3
DESCRIBE CIRCUMSTANC	CES OF THE ACCIDENT
OP.	Police Report 7/20200603/2018
Kefer	1046 report 1/2020603/3018
	<i>y</i>
Y	
ECLARATION	Λ /.
	ticulars are true in every respect.
COMFORT TRANSPO CO. REG. NO. 1	RTATION PTE LTD
licyholder's Signature	Driver's Signature Reporting Centre Personnel's Signature
te & Time:	(If driver is not the policyholder) Name: NRIC/FIN No.:





Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No: 1800-5852999

Report No. T/20200603/2018

1 of 3

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: Vide Report No.: Station Diary No.: 03/06/2020 10:30 28 Informant's Particulars Name of Informant: Address: HUSSIN BIN IDRIS APT BLK 109 ANG MO KIO AVENUE 4 #12-26 SINGAPORE 560109 ID Type / ID No.: Contact No.: NRIC NO / S1310839J Home/Office: Mobile: 96248328 Nationality: Email: SINGAPORE CITIZEN Sex: Age: Date of Birth: Type of Informant: 62 Male 02/05/1958 Driver Race: Language: Institution / School Name: Malay English Occupation: Driving Licence Information: Taxi driver Date of Expiry: Class: 3

Type of	Non-Injury	Drink	Date/Time of	Type of Location:
Type of Accident:	Hit and Run	Drive: No	Accident: 03/06/2020 08:00	Straight Road
Location: Along Road 1 ANG MO KIO		. 3		
Weather:	Varus Ang IVIO NIO AVE	Road Surface:	F	Road Speed Limit:
Clear		Dry		50 Km/h
Traffic Flow:	B 1000	Traffic Control: Traffic Light - Wor		raffic Volume: leavy
Two Way				

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SHD4044G	Car				Seriously Damaged	(23,5)
YN8297M	Lorry					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Tel No: 1800-5852999

2 of 3

Report No. T/20200603/2018

Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457

CONTINUATION OF REPORT

Driver									
Name	HUSSIN BIN IDRIS					S1310839J			
Related Vehicle	NIL			NIL		NIL Conta		ict No.	96248328
Hospital/Clinic	NIL			Class Drivin Licen Expire	g	Class: 3 Date of Expiry: NIL			
Date Treatment	NIL		Date Disc	harge	NIL				
No. of Days gran	ted Medical Leave	NIL	Degree of	f Injury	NIL				

Brief Details.

On 03/06/2020 at about 0800hrs I was driving my taxi travelling along Ang Mo Kio Ave 10. I was at a traffic light junction turning right onto Ang Mo Kio Ave 3. I was waiting for my turn on the right turn lane. There were 5 to 6 cars in front of me. Suddenly a lorry cut into the right turning lane where I was waiting. As the result the lorry side swiped the left side of my taxi. It caused my left side mirror to be damaged and there is also dent and scratches on the left side of my taxi.

The lorry did not stop after the accident.





Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457

3 of 3 Report No. T/20200603/2018

Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
Sr Staff Sgt HUANG ZHENJIE	Je Je
Signature Of Interpreter:	Date/Time:
Not applicable	03/06/2020 10:30
Officer In Charge Of Case:	Classification Of Case:
Inon COH CEOK I VE	
Contact No.: 65476148	
Authentication Stamp	
1.000.00 mm (1.000.00 mm)	