



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	003M
<b>Vehicle Details</b>	
Vehicle No.:	XE7088R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2020
Vehicle Make:	HINO
Vehicle Model:	FY1EUMA-KAS
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	E13CWA10928
Chassis No.:	FY1EUM10018
Maximum Power Output:	-
Open Market Value:	\$87,049.00
Original Registration Date:	08 May 2015
First Registration Date:	08 May 2015
Transfer Count:	1
Actual ARF Paid:	\$4,353.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 May 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$26,087.00
<b>Total Rebate Amount:</b>	<b>\$26,087.00</b>

The information contained herein is correct as at 05 Jun 2020

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	04/06/2020 11:10
Date Of Accident	02/06/2020 17:40
Exact Location Of Accident	ALONG BAH SOON PAH ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE7088R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TKB C-E CONTRACTOR PTE LTD
Co Reg No	1XXXXX003M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62535422
<b>Vehicle Particulars</b>	
Manufacturer	HINO
Model	FY1EUKA-12.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSNW00031082002
Cover Note Number	
<b>Driver</b>	
Name of Driver	THANGARAJAN ARIVALAGAN
NRIC No	GXXXX756T
Date Of Birth	20/01/1982
Occupation	OUTDOOR
Date Of Driving Pass	14/10/2015
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85547798
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	C/O 3 PEMIMPIN DRIVE #05-04 LIP HING INDUSTRIAL BUILDING
Postcode	576147
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	AFTER RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KARUBIYA
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC7197A
Vehicle Make/Model/Colour	VOLVO S60
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG HOCK BENG
NRIC/Passport Number	SXXXX344A
Contact Number	
Address	48 CANBERRA DRIVE #15-13
Postcode	768437
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: - 4 JUN 2020

S. Arivalagan.

Driver's Signature

(If driver is not the policyholder)

Date & Time: - 4 JUN 2020

dm

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Jenny Lim

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/06/2020, I was driving along Beh Soon Pah Road on my way going back to my company site office. Suddenly, the vehicle B (5MC7197A) came out from the right junction (Pioneer Garden Services) and hit onto right side of my front vehicle caused my front right side tyre, wheel rim and front portion was damaged.

## DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature  
Date & Time:

- 4 JUN 2020

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

- 4 JUN 2020

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Jenny Lim



M/S: China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Tel: 6389 6111 Fax: 6225 3592

Attn: Motor Claim Department

## ESTIMATE

GST Regn No.: 200516575H

Co. Regn No.: 200516575H

Estimate No.: E2006001

Date: 04/06/2020

Accident Date: 02/06/2020

Claim No.: TP Claim

Policy No.: DMCVSNW00031082002

Chassis No.: FY1EUM10018

Year: 2015

Make & Model: Hino FY1EUMA-KA

Vehicle No.: XE7088R

S/No	Description	Qty	Unit Price	Amount
List Item:				
1	Front Bumper / CRU	1	\$ 2,498.00	\$ 2,498.00
2	Front Bumper Reinforcement / BT	1	\$ 568.00	\$ 568.00
3	Front Bumper Garnish RH X	1	\$ 153.00	\$ 153.00
4	Front Bumper Side Bracket RH / BT	1	\$ 210.00	\$ 210.00
5	Front Bumper Side Panel RH X R	1	\$ 395.00	\$ 395.00
6	Head Lamp Assy RH c/w ECU / SCR	1	\$ 3,250.00	\$ 3,250.00
7	Front Step Garnish RH / CRU	1	\$ 475.00	\$ 475.00
8	Front Step Garnish Cover RH / MIS	1	\$ 174.00	\$ 174.00
9	Front Step Garnish Reflector RH / CRA	1	\$ 136.00	\$ 136.00
10	Front Tyre Rubber Mudflap RH / CRU	1	\$ 155.00	\$ 155.00

- List Item Discount 10%

\$ 8,014.00

\$ 801.40

\$ 7,212.60

### Special Nett Item:

photo from workshop	1	Front Tyre RH 295/80R22.5 / BR	1	\$ 650.00	\$ 650.00
	2	Front Wheel Rim RH / BT	1	\$ 450.00	\$ 450.00
	3	Front Step Garnish Clip / NEC	15	\$ 3.50	\$ 52.50
	4	Front Bumper Reflective Sticker / NEC	4	\$ 15.00	\$ 60.00
	5	Front Bumper Side Panel Reflective Sticker RH / NEC	1	\$ 15.00	\$ 15.00
	6	Front Door Reflective Sticker / NEC	1	\$ 15.00	\$ 15.00
				\$	1,242.50

## CONVINCE AUTO PTE LTD

176 Sin Ming Drive #04-04 Sin Ming Autocare Singapore 575721  
Tel: +65 6556 1131 Fax: +65 6553 1131 Email: convinceapl@convinceauto.com.sg



M/S: China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Tel: 6389 6111 Fax: 6225 3592

Attn: Motor Claim Department

## ESTIMATE

GST Regn No.: 200516575H

Co. Regn No.: 200516575H

Estimate No.: E2006001

Date: 04/06/2020

Accident Date: 02/06/2020

Claim No.: TP Claim

Policy No.: DMCVSNW00031082002

Chassis No.: FY1EUM10018

Year: 2015

Make & Model: Hino FY1EUMA-KA

Vehicle No.: XE7088R

S/No	Description	Qty	Unit Price	Amount
<b>Labour:</b>				
1	To Repair Panel Beating, Cut, weld, Straighten Front Inner Panel, Chassis Frame, Front Door Lower Garnish & Repalce Above Parts On Damaged Area.	1	\$ 1,000.00	\$ 1,000.00 750
2	To Putty & Spray Painting Front Inner Panel, Front Door Lower Garnish RH, And Affected Area.	1	\$ 1,200.00	\$ 1,200.00 750
3	To Apply Anti-Rust	1	\$ 150.00	\$ 150.00 60
4	Check Wiring Function	1	\$ 120.00	\$ 120.00 30
5	Computerized & Resetting For Head Lamp System	1	\$ 180.00	\$ 180.00
6	To Check Head Lamp Focus	1	\$ 80.00	\$ 80.00 } 50
7	To Check Side Slip	1	\$ 150.00	\$ 150.00
				100

Labour Item:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:  
Date:

\$ 2,880.00

TOTAL : \$ 11,335.10

GST 7% : \$ 793.46

Total Amount : \$ 12,128.56

CONVINCE AUTO PTE LTD

4 days - Repair dy - 4 days

. L/S  
After paint photo

Sun Pm (LKK)  
04/06/2020  
TP without prejudice

## CONVINCE AUTO PTE LTD

176 Sin Ming Drive #04-04 Sin Ming Autocare Singapore 575721

Tel: +65 6556 1131 Fax: +65 6553 1131 Email: convinceapl@convinceauto.com.sg