(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/ CT120006147/USF3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMS 34SSE

at Workshop m/s Kah Motor

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 58k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1,331 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 068C

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMS 3558E Yr Regn: 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA1

Make: Honda city OPC c.c 1497

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 3558 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHGM6660LT000193

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm
D.O.A.	17/5/20	D.O.I.	8/6/20

Survey held at —

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rr.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA 3072 new car 66k.
23/6/20	confirmed final fig $ 1864.58 with rueben.
	($ 1,752.08/RED - 48%)

Date/Time, File Pass to? 23/06/2020

1) TYPIST

Date/Time, File Return to?

2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: $ 1,864.58 P/P)