

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **GBF 6665 L**
Your ref: **SH 8592 M**

08 June 2020

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : HWA KOON ENGINEERING PTE LTD
VEHICLE NUMBER : GBF 6665 L
YOUR INSURED VEHICLE NUMBER : SH 8592 M
ACCIDENT ON 07 June 2020 ALONG UPPER SERANGOON ROAD / POTONG PASIR AVE 1
AT ABOUT 15:00 HOURS

We refer to your email/fax dated **08 June 2020** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921

Contact Person: **6842 0051 / 6744 0510 (Melody)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: